

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD


T. 47 N.R. 16 W
Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner for 7

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9-21-61

WITNESSES TO CORNER..... 8" Sugar (NBT 1/4S) N22°E 27 links



12" Sugar (NBT 1/4S) S10°E 18 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from wood stake and old rotted post (down). Sugar stump to SW badly rotted, could be possible B.T. Old road to NE could have destroyed sugar to NE.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE December 29, 1961
REGISTERED LAND SURVEYOR
Billy D. Buckler