

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47N N.R. 16W


Schoolcraft COUNTY

DESCRIPTION OF CORNER East 1/16 corner bet. Secs. 2-11

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 11-6-69

WITNESSES TO CORNER..... 8" cedar (1/16 BT) N27°E 12.4'



9" cedar (1/16 BT) S7°E 22.3'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line between Sec. Cor. to east and  $\frac{1}{4}$  Cor. to west.

Corners lie in swamp.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1-26-70  
REGISTERED LAND SURVEYOR