MAY 28 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

96 NOV 18 PM 3: 39

REGISTER OF DEEDS Laye Lusta

Ear	 i m	

Shiawassee (County)		Located in:		Corner Code #
1. Public Land Survey		Т <u>5</u>	N R 2E	
		<u> </u>	R R	
		<u>,</u> –		
2. Property Controlling	s	T	. R	
in Section	s	T	R	
3. Miscellaneous	s	т	R	
Property in Sec.	s	т	R	
4. Lot No	, Recorded Plat			
Private Claims				

I, Mark L. VanRaemdonck, in a field survey on November 6, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the current points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 1.) Original: Joseph Wampler, D.S., 1826.

Monument: Wood post
Accessories: Hickory 6 S5°E 9

W. Oak 6 N34°W 8

2.) M. VanRaemdonck, L.C.R.C. recorded Liber 2, page 847, 1/8/93.

Monument: Re-established location of NE corner of Section Northwest corner of Section 30, T5N-R3E Section 25, T5N-R2E, at G.L.O. jog a distance of 0.06 chains South of the

North 3.96' R.R. spike at NW corner Section 30, T5N-RE S30°E 53.78' P.K. in E. face util. pole N50°E 49.07' Top cen. tel. cable box N65°E 90.16' Set N&T S. face util. pole

3.) M. VanRaemdonck, survey recorded Liber 6, page 392, 1/8/93.

Monument: None given.

Accessories: Same as no. 2 above.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found P.K. and tag #24622 as referenced in no. 2 and no. 3 above. I accepted this location as the careful and faithful re-establishment of the original corner position based on the best available evidence. Excavation for Harrison Marker provided no further evidence. Found no conflicting evidence.

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

Installed a standard Shiawassee County Harrison Marker monument at the location described above. The monument is stamped "REMON 24622" and is witnessed by the following accessories: OF MICHIGA

N60°E 54.54' Set mag nail & tag in W. face 24" Walnut N30°W 38.92' Set mag nail & tag in W. face 10" Elm S30°W 53.52' Set mag nail & tag in W. face util. pole

S50°W 61.18' E. edge road sign post

Signed by Mak L. Van funds

No. 24522

MARK L ANRAEMDONC

> LAND SURVEYOR

Ą

Surveyor's Michigan License No. 24622

BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971; REVISED MAY 14, 1975 REVISED JAN., 1983

3 4 5

6

7 8

9 10

11

12

13

County Remonumentation Peer Review Group