SURVEY &

LAND CORNER RECORDATION CERTIFICATE

2000 Remonumentation Program

JAN 1 6 2001

Filing Requirement of Act 74, Mich. P.A. 1970

RECTION

F	COTHERS	
FOR	COLUMN	ın

SHIAWASSEE (County)	Located In: Venice Twp.	Corner Code	Kaye Grubba			PENO.		3044 Page 12/04 L-1	418 4/2000 P-356	1 09:53A		
1. Public Land Survey	T <u>7N</u> R <u>4E</u> T R T R	<u>C-7</u>		Register		ds Star	np&F	ile Num	ıber			
2. Property Controlling Sin Section S 3. Miscellaneous S Property In Sec. S	T_7N R4E T R T R T R T R T R T R		APPRO County Remor	N Grout	מ			•				
				1,	A B (D 1	E F (3 H I	I J K	L N		
4. Lot No, Recorded Plat 5. Private Claims				- 2 - 3	6	5	4	3	2	***		
I, <u>John H. Rauser, P.S.</u> , in a field survey on <u>August 14</u> 20 00 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					7	- 8		10	11	12		
					6	17-	16	15	14	13		
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of Court of Law; established, re-established, monumented, re-monumented, recovered, found a			cree of a o	19	20	-21	22	23	24			
expressed below:				10	30	29	28	-27	26	25		
NOTE: Not more than 4 corner on this certification		town and range	e, may be recorde	12	31	32	33	34	35	36		
A. Description of original monument and accessories and/or subsequent restoration: Section Corner common to Section 17, 18, 19 & 20, T7N-R4E, Venice Township, Shiawassee County 1822 GLO notes by J Wampler D.S., Wood post, witnessed by S54W 16 links (10.56') 6" Ash, N30W 29 lks (19.14') 9" Ash,												
measured 40 ch 1950 MDOT State Hig 1965 record of minute given 1976 MDOT right of w	measured 40 chains (2640') C-7 to C-8 1950 MDOT State Highway M-21 construction plans, Proj. No. F-45(5), State Proj. 76-17 1965 record of minutes of survey by John F. Quine #10704, iron in monument box as noted in highway plans, witnessed-none given 1976 MDOT right of way plans, file No. 76-R-1 Sheet 56, Monument description-none given, witnessed by 2.05' North of C/L											
1985 LCRC 2, P.42	M-21, Measured C-7 to C-6 2637.95'											
1994 Certified Survey 1995 Certified Survey comer conc. cur West end concre	1994 Certified Survey, L.7, P.50 and											
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Section Corner common to Section 17, 18, 19 & 20, T7N-R4E, Venice Township, Shiawassee County Found no evidence of the original government corner or accessories. Found boat spike in monument box at approximate intersection of M-21 and Vernon Road, 6'+_North of the center line of M-21. Measured North to C-6 = 2637.86', South to C-8 = 2638.30', and West to A-7 = 6134.70' (GLO = 6131.40'). Found no conflicting evidence in the vicinity of this corner. We recommend accepting the found boat spike in monument box as the best available evidence of the position of the original government corner and replacing it with a standard Shiawassee County Harrison												
monument in existing r		nd accessories	established to	perpetua	ite loca	iting th	ie pos	ition o	f the			
comer: C-7 Section Corner common Set standard Shiawasses	to Section 17, 18, County Harrison	19 & 20, T7N-R4 monument	IE, Venice Townsh	njp, Shiawa	assee C	ounty	Milesey Man.		Ŋ			
\$29W 65.28' Set nai \$35E 78.44' Found N20F 56.51' Found	NF corner of end	NW face of cut of all & brass tag in a of curb in NE qua	8" Elm ff utility pole SW face power po ad of M-21 & Vern uad of M-21 & Vern	on Road	A LICENSED	PROFE SURV	MICA IN H. JSER SSIONA VEYOR IO.	SELON X HAD	11/0	9/16		