SURVEY & MONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

2000 Remonumentation Program

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

JAN 1 6 2001

SECTION

SHIAWASSEE (County)	Located in: Venice Twp.	Corner Code	Kaye Grub	bba — Shlawa	stee Co	. REI	ON	304 Per 12/		7 13 2 09 53 8	
1. Public Land Survey	T 7N R4E C-9 T R Register of Deeds Stamp T R							np & File Number			
Property Controlling S	T R T R T R T R		County Peer	PRO! Remonur	VEI	D ion	F F 6		J K	LN	
4. Lot No, Recorded Plat			Peer	Review ¹	Group	5	4	3	2	-	
5. Private Claims				3 4	7	8	9	10	-11	12	
I, John H. Rauser, P.S., in a field survey on August 20 00 . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 6 current manual of survey instructions of the United States Department of the Interior, Bureau of Land 7						-17	-16	15	14	13	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 8 Court of Law; established, re-established, monumented, re-monumented, recovered, found as of					19	20	-21	-22	23	24	
expressed below: NOTE: Not more than 4 corners				10	30	29	28	27	26	25	
on this certificate.	s, an in the same	town and range,	, may be recen	12	3.1	32	33	34	35	36	
 1822 GLO notes by J Wampler D.S., Wood post, witnessed by N70W 14 links (9.24') 6" fronwood, S20W 16 lks (10.56') 8" fronwood. North, C-8 to C-9 40 chains(2640'). Undated field notes, CR ?, P.75, 2" solid iron 1.5' below railroad spike, witnessed by NE 36.00' iron fence post, No direction 59.60' P. pole, SW 54.7' 30" Twin Elm stump, West 52.7' Power pole 1975 Act 74, L.1, P. 477 by John F. Quine #10704, Find. 2" iron 1.5' below RR spike on surface of road, witnessed by WSW 51.75' center of P. pole, NE 39.00' center of road name sign, NE 36.3' center of 2" angle iron corner fence post, SE 60.1' center of Power pole. Note: also found 1" IP 1.0' West and 0.2' South of corner. 1990 Certified Survey L.5, P.865 by Mark VanRaemdonck #24622, Find. RR spike 6" below surface, witnessed by S25E 60.43' set N&T East face utility pole, S80W 51.83' set N&T South face utility pole, N45E 40.60' top center of tele. Cable box, S40E 46.38' top center of tele. Cable box. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Section Corner common to Section 19, 20, 29 & 30, T7N-R4E, Venice Township, Shiawassee County 											
Found no evidence of the original government corner or accessories. Found ½" rod with cap #24622 in monument box at approximate intersection of Lennon and Vernon Roads. Measured North to C-8 = 2627.37', and West to B-9 = 2630.78', Found no conflicting evidence in the vicinity of this corner. During excavation we found a 2" iron bar below the ½" rod. We recommend accepting the found rod and 2" iron bar as the best available evidence of the position of the original government corner and replacing it with a standard Shiawassee County Harrison monument and monument box. C. Description of monument for corner and accessories established to perpetuate locating the position of the											
corner.				•			re posi	tion of	the	Ĩ	
C-9 Section Corner common t Set standard Shiawassee	County Harrison	monument and m	nonument box.	ынр, эпіа <u></u>	assee C	<u>ourity</u>	÷				
N50E 36.28' Southw S80W 51.69' Found r	l & tag #39096 in sest corner of 2" at nail & tag #24622 inter of cable box	ngle iron fence po	st	[*/ i	OF MI	R	THE REAL PROPERTY OF THE PARTY				
Signed by Surveyor's Michigan License No	, J. K	ausy			OFESSIO SURVEYO No. 39096	OR A	BOARD	OF LAND SU		JAN. 28, 197	