For corners in COMMISSION

APR 08 1996

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Shlawassee (County)	Located in:	Corner Code	#	RECORDED	
(003,)				95 NOV 22 PM 1:18	
1. Public Land Survey	T 8N R 1E	(M-13)		REGISTER OF DEEDS	
(. 1 abilo abile obive)	TR			They hulla	
	TR TR			SHIMMASSET COUNTY, MICH.	
2. Property Controlling	s			V	
In Section 3. Miscellaneous	STR STR		i i	Register of Deeds Stamp & File Number	
Property in Sec.	srR			negister of Deeds Stamp & The Rumber	
	, Recorded Plat			A B C D E F G H I J K L M	
5. Private Claims	, Nebolada i ist			2 - 6 5 4 3 2 1 - 1	
				3 4 7 8 9 10 11 12	
				5	
requirements of P A 74 M	in a field survey on October 12 Michigan P.A. of 1970, the corne	r points mentione	d in lines 1 and 2	6 - 18 - 17 - 16 - 15 - 14 - 13 -	
above were in conformance	ce with regulations and rules the one of the United States Departr	nerefore as requir ment of the interio	ed in the current r. Bureau of Land	7	
Management or by a decr	ee of a Court of Law and/or there in conformance with the rule	at the current poi	nts mentioned in	9	
Surveyors or by a Decree monumented, recovered, for	of a Court of Law; established	l, re-established,	monumented, re-	10 - 30 - 29 - 28 - 27 - 26 - 25	
		a town and ran	MA.	11	
may be recorded on t	n 4 corners, all in the same his certificate.	e town and ran	gc,	12 31 32 33 34 35 36	
A. Description of original	monument and accessories and/	or subsequent res	toration:		
1.) Original: Joseph Wampler, D.S.			3.) M. VanRaem	donck - Survey recorded Liber 4, page 378, 8/13/95	
Monument: Wood stake Accessories: Beech 16 S20°E 11			Access	ent: Rerod & cap #24622 ories: Same as #2 above	
Iro	on wood 7 N13°W 26		4.) M. VanRaem	donck - Survey recorded Liber 5, page 328, 6/22/89	
2.) M. VanRaemdonck - Survey recorded Liber 4, page 239, 7/24/84 Monument: Set rerod & cap #24622 at proportional measurements North, South, East and West			Monument: Rerod & cap #24622 Accessories: Same as #2 above 5.) M. VanRaemdonck - Survey recorded Liber 6, page 63, 11/4/91		
Accessories: N50°E 75.04' P.K. in S. face 18" Linden N45°W 44.60' SE face road sign post		" Linden post	6.) M. VanRaemdonck - Survey recorded Liber 6, page 293, 7/20/92		
N-	40°E 49 35' Top cen. bolt cable orth 7'± Centerline-centerli	e box	Monume	ent: Rerod & cap #24622 ories: Same as #2 above	
	surfaces		•		
	·				
•	vidence found and/or method ap				
Found rerod & cap #24622	as reference in no.'s 2, 3, 4, 5 a	and 6 above. Four	nd no conflicting evi iul re-establishmen	vidence. Excavation for Harrision Marker did not nt of the corner location based on the best available	
evidence.	o. Modelica inio promon an		•		
			!		
		•	ł		
	nt for corner and accessories to				
Replaced rerod and cap wit S45*E 26.46' Rerod & ca	th standard Harrision marker sta	mped "REMON 24	1622" and is witnes	ssed by the following accessories:	
\$45°W 34.09' Rerod & ca	ıp #24622			OF MICHAEL	
N45°W 46.61° E. edge roa N45°E 48.33' Top cen. te		nnna	/ED	T-STATE OF THE STATE OF THE STA	
	_	PPRO'		MARK L. VANRAEMDONCK	
	Cou	nty Remonul	nentation	LAND ** SURVEYOR	
	P &	eer Review	Group 5 MLV	No. 24622	
. /	1.10			Market Commence	
Signed by	L. Van Kande	_h_	Date _ No	V. 16, 1995	
Surveyor's Michigan Lice	nse No. <u>24622</u>		FORM APPRO	VED BY MICHIGAN STATE BOARD OF LAND SURVEYORS JAN 18, 1971) REVISED MAY 14, 1975	
	linen	n/	• • •	REVISED JAN , 1983	
	TIRFK	R PG	121		