

**1997 REMONUMENTATION PROGRAM  
LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD  
LIBER NO. \_\_\_\_\_ PAGE NO. \_\_\_\_\_  
FILE NO. # 39  
ELLINGTON TOWNSHIP  
97 OCT -7 PM 3:02  
*Jonathan M. Field*  
TUSCULA COUNTY  
REGISTERED SURVEYORS

For corners in: ELLINGTON TWP.

TUSCULA (County)	Located In:	Corner Code #
1. Public Land Survey	T 13N R 10E	C-13
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

**Register of Deeds Stamp & File Number**

4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, JONATHAN M. FIELD, in a field survey on JULY 24 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:  
1834 GLO; PARKE, D.S.; SET POST; HEMLOCK 15 N76W 40LKS. BIRCH 7 N56E 19 1/2LKS.  
1976 ROWE, P.S.#11192; LCRC PG.20; FND. ABUNDANT CROCKERY AROUND CHARRED CEDAR POST SET 1/2' ROD; EAST 52.60' NE COR. SEC.6, S40E 38.95' NAIL 8" POPLAR, N45W 39.80' TAG #11192 IN COR POST, N40E 58.77' NAIL W/CAP IN 8" PINE, N45E 69.30' NAIL W/CAP IN 8" PINE, N70E 54.95' TAG #11192 IN POST, S70E 90.45' FACE OF ROAD SIGN POST  
1976 ROWE; ROWE, P.S.#11192; SURVEY L.461 PG.181-182; WITS FOR C-1 T12N-R10E INCLUDE WEST 52.60' TO ROD, CEDAR POST & CROCKERY AT C-13 T13N-R10E  
1977 ROWE; DUNTON, P.S.#23503; SURVEY L.474 PG.242-243; SAME REFERENCE AS 1976 ROWE SURVEY ABOVE  
1977 ROWE; DUNTON, P.S.#23503; SURVEY L.474 PG.240-241; SAME REFERENCE AS 1976 ROWE SURVEY ABOVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
1997 ROWE; FIELD, PS#37276; FND. 1/2" ROD; RECOVERED 2 PREVIOUS WITNESSES WHICH INDICATE THAT FND. ROD IS IN SAME POSITION AS 1976 ROWE LCRC CITED IN SECTION A. ABOVE; ALSO FND. PIECES OF CROCKERY BELOW FND. ROD

ACCEPTED FND. ROD AS THE BEST AVAILABLE EVIDENCE OF THE ORIGINAL CORNER POSITION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
C-13 REPLACED FND. ROD W/ STD. REMON. MONUMENT STAMPED C 13 T13N R10E  
EAST, 52.31' FND. T-IRON APPARENT C-1 T12N-R10E  
S06°E, 38.42' SET NAIL W/TAG #37276 IN W. FACE 6" POPLAR  
N36°W, 27.58' SET NAIL W/TAG #37276 IN SW FACE 10" POPLAR  
S61°W, 56.67' SET NAIL W/TAG #37276 IN NW FACE 4" PINE  
N46°E, 58.97' SET NAIL W/TAG #37276 IN NW FACE 18" PINE



Signed by *Jonathan M. Field* Date 9-24-97  
Surveyor's Michigan License No. 37276

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1993  
ADAPTED FOR WORD PROCESSING MARCH, 1993

APPROVED  
9-22-97  
*M.P.A. J.P.R. 5215*

SURVEY &  
REMONUMENTATION  
NOV 26 1997  
COMMISSION

