

SURVEY & REMONUMENTATION

FILED

JAN 14 1998

NW corner, Sec. 7

DEC 17 3 05 PM '97

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Antwerp Township

Van Buren
(County)

Located In:

Corner Code #

Mark A Smith
VAN BUREN CO.
REGISTERED PROFESSIONAL SURVEYOR

- | | | | | | |
|------------------------------------|---|-----|---|------|-----|
| 1. Public Land Survey | T | 3S. | R | 13W. | A-3 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Section | S | | T | R | |

Liber 5 Page 64

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Allen H. McMachen, in a field survey on December 4, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1829 - William Brookfield, D.S., "...Intersected West boundary 2.80 chains (184.8') North of post.

1927 - T.A. Smith, C.S., Prepares "Marshall Peninsula" survey showing corner 184.8 feet North of Paw Paw corner. Survey also shows a property corner 2 feet South and 2 feet West of Section corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No marker was found. Placed a standard Van Buren County Remonumentation Monument from (8) corners recovered from the 1927 "Marshall Peninsula" survey and also holding Government jog of 184.8 feet North of the Paw Paw corner. Monument at location previously mentioned was ratified by the Van Buren County Remonumentation Peer Group on August 27, 1997.

Ratified by Peer Group in
accordance with P.A. 345 of 1990
Van Buren County Surveyor

Date D.R.G. 12/17/97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

The standard Van Buren County Remonumentation monument placed is accepted as the best available evidence of the position of the corner, Accessories:

- Drill hole (existing) in concrete driveway S. 45° W. 2.8'
- S.W. corner concrete block garage N. 30° E. 40.50'
- Nail in Southerly side of utility pole S. 65° E. 38.17'
- Nail in Northerly side of 10" Cedar S. 55° W. 44.05'
- Nail in Northeasterly side of 36" Maple S. 35° E. 29.17'

Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 12/8/97

