

JAN 14 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
VAN BUREN COUNTY REMONUMENTATION

DEC 23 8 59 AM '97

SECTION

For corners in
VAN BUREN
(County)

Located In:

Corner Code #

1. Public Land Survey
SE COR SEC. 32
SW COR SEC. 33
DECATUR TWP.
T 4S R 14W E-13
T R
T R
T R
2. Property Controlling
in Section S T R
S T R
3. Miscellaneous
Property in Sec. S T R
S T R

Mark A. Smith
VAN BUREN CO.
REGISTERED SURVEYOR

Liber 5 Page 25

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, DALE L. KESLER, in a field survey on JULY 23, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- * 1827 WILLIAM BROOKFIELD. SET POST COR. TO SECTIONS 32 AND 33. 12" BEECH N 73 3/4 DEGREES W 23 LKS., 16" ASH N 72 DEGREES E 50 1/2 LKS.
- * JUNE 9, 1990 GEORGE MUTCHLER, COUNTY SURVEYOR, STAKE AND REMAINS OF ONE WITNESS TREE. REWIT: 16" BEECH SOUTH 50 DEGREES W 25 1/4 LKS., DRAWING SHOWS VAN BUREN CORNER EAST OF CASS'S CORNER 9.9'
- * FEB. 28, 1924 T.A. SMITH. SECTION CORNER FOR DECATUR TOWNSHIP IS 10' EAST OF CORNER FOR VOLINIA TOWNSHIP.
- * NOV. 9, 1992 S.W. SURVEY & ENGINEERING CO., RECORDED SURVEY IN LIBER 10, PAGES 72 & 73. FOUND IRON. WITNESSES: E 462.00' CENTERLINE OF 42ND STREET, N 04 DEGREES 01'39" W 652.94 1/2" I.R., N 10 DEGREES 34' 28" E 696.90 1/2" I.R., N 05 DEGREES 42'28" W 859.78 1/2" I.R.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1" IRON PIPE. DISTANCE TO ADJACENT CORNERS WERE REASONABLE. ACCEPTED THE 1" IRON PIPE AS BEST EVIDENCE OF CORNER. THE GOVERNMENT MONUMENT WAS RESTORED WITH APPROVAL OF THE VAN BUREN COUNTY REMONUMENTATION GROUP OF SURVEYORS AT A MEETING HELD ON OCTOBER 29, 1997, AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- SET HARRISON MARKER IN PLACE OF 1" IRON PIPE.
NAIL & TAG 26" OAK S 27 DEGREES W 23.70'
NAIL & TAG 12" BEECH S 88 DEGREES W 28.20'
NAIL & TAG 16" CHERRY NORTH 35.40'
NE CORNER SEC. 5 & NW CORNER SEC. 4, T5S, R14W EAST 7.92'



Signed by Dale L. Kesler
Surveyor's Michigan License No. 38117

Date 12/22/97

Ratified by Peer Group in
accordance with P.A. 345 of 1990
Van Buren County Surveyor

Date D. R. S. 12/23/97