

FEB 28 1994

RC 1227

L127004PA583

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing requirement of Act 74, Mich. P.A. 1970

For corners in WAYNE COUNTY (County) Located In: Corner Code #

1. Public Land Survey	T <u>1 S</u>	R <u>9 E</u>	<u>1-9</u>
	T _____	R _____	_____
	T _____	R _____	_____
	T _____	R _____	_____
2. Property Controlling in Section	S _____	R _____	_____
	S _____	R _____	_____
3. Miscellaneous Property in Sec.	S _____	R _____	_____
	S _____	R _____	_____

Compliance with ACT 345, P.A. 1990

APPROVED ON: 12/3/93 YMO

WAYNE COUNTY REMONUMENTATION PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, ROBERT J. SMALLEY, in a field survey on NOVEMBER 29, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the cornerpoints mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

- GLO (1816): "POST"
- WPA (1930's): "MON NW-26"
- LCRC (1981): "FOUND IRON BAR IN MONUMENT BOX" (RC-50; L. 18022, P. 17)

FOREST COUNTY REGISTER OF DEEDS  
 REGISTERED  
 93 DEC -3 PM 12:41

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1" IRON BAR IN MONUMENT BOX AS DESCRIBED IN RC-50; WITNESSES RECORDED IN RC-50 HAVE ALL BEEN DESTROYED; WAYNE COUNTY SURVEY SECTION MAP SHOWS DISTANCE TO CORNER I-10 TO BE 2646.92'. PREVIOUS SURVEY WORK BY DAVID C. ADAMS AND SON (1987) SHOWS DISTANCE TO BE 2647.23'. ACCEPTED POINT I-9 AS FOUND.

2R  
11D  
M

C. Description of monument for corner and accessories to perpetuate locating the position of the corner:

FOUND 1" PIPE IN MONUMENT BOX AT INTERSECTION OF MERRIMAN ROAD AND E. BOUND SCHOOLCRAFT ROAD SERVICE DRIVE; WIRED "WAYNE COUNTY REMONUMENTATION" TAG TO IRON BAR IN BOX.

- N. 55° W. 55.14'; CENTERLINE OF SOUTHEAST BOLT OF CONCRETE LIGHT POLE BASE.
- N. 25° E. 131.46'; CENTERLINE OF SOUTHEAST BOLT OF CONCRETE SIGN BASE.
- S. 45° E. 54.36'; CENTERLINE OF NORTHWEST BOLT OF CONCRETE LIGHT POLE BASE.
- S. 16° W. 137.22'; CENTERLINE OF NORTHEAST BOLT OF CONCRETE LIGHT POLE BASE.

THE SELECTED LOCATION IS ACCEPTED BY THE CONTRACTOR AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE BEST AVAILABLE EVIDENCE OF THE ORIGINAL CORNER.

Signed by Robert J. Smalley Date Nov. 30, 1993

ROBERT J. SMALLEY

Surveyor's Michigan License No. 26467

