

LAND CORNER RECORDATION CERTIFICATE
APR 05 1996 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

WAYNE

(County)

COMMISSION

Located In:

GREENFIELD TWP
(NOW CITY OF DETROIT)

Corner Code #

1. Public Land Survey

T 1S R 11E

1-5

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous
Property in Sec.

S T R
S T R

Compliance with
ACT 345, P.A. 1990

APPROVED ON: DEC 5 1995 ncl
WAYNE COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	8		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, STEVEN E. DUNN, in a field survey on OCTOBER 8, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO POST - NO EVIDENCE OF ORIGINAL CORNER FOUND

GLO ORIGINAL SURVEY PERFORMED BY JOSEPH FLETCHER UNDER CONTRACT DATED SEPT., 1816

PLATS

L. 28 P. 52
L. 31 P. 52

HAMILTON PARK
LOG CABIN HEIGHTS

NOVEMBER 12, 1912
OCTOBER 23, 1914



95263075

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

NO EVIDENCE OF CORNER FOUND.

RE-ESTABLISHED CORNER USING FOUND IRONS AND RECORD ANGLES WITH REFERENCE TO PLATS LISTED ABOVE.
VERIFIED LOCATION WITH CURB AND WALK SPLITS.

PLACED WAYNE COUNTY REMONUMENTATION MARKER AND ALUMINUM CAP #28408 ON 1/2" x 18" IRON
WITHIN A MONUMENT BOX.

FOREST E. YOUNGBLOOD
REGISTERED PROFESSIONAL SURVEYOR

95 DEC -8 PM 2:10

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1-5 T.1S, R.11E. WAYNE COUNTY REMONUMENTATION MARKER AND ALUMINUM CAP #28408 ON 1/2" x 18" IRON IN A MONUMENT BOX.

WITNESSES

AZ. 33° 33.04' SET PK NAIL WITH TAG IN SOUTHEAST FACE OF UTILITY POLE
AZ. 116° 60.08' SET PK NAIL WITH TAG IN NORTHEAST FACE OF 30" OAK
AZ. 244° 62.85' SET PK NAIL WITH TAG IN CONC. SIDEWALK
AZ. 287° 86.97' SET PK NAIL WITH TAG IN SOUTHWEST FACE OF UTILITY POLE

4
7D
n.s.

THE SELECTED LOCATION FOR THIS PROPERTY CONTROLLING MONUMENT IS ACCEPTED AS A CAREFUL AND FAITHFUL DETERMINATION OF THE POSITION AS INDICATED.

Signed by Steven E. Dunn

Date DECEMBER 5, 1995

Surveyor's Michigan License No. 28408