APR 2 5 1995

POST FOR NORTH CORNER COMMON TO

SECTIONS 4 & 5, T3S, R10E WEST-1.38 CHAINS (91.08')

RC 1418

LI27792PA275

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

JOHNEY HEGONDAHON CENTILL	CAIE		
Filing Requirement of Act 74 Mich PA	1076 13.00	MISCELLANEOUS	RECORDING
Filing Requirement of Act 74, Mich. P.A.	ZI DEC 9	74 8:24 A.M.	RECEIPT# 16
1		\$ 17 TET	

For corners in	i ming medune	ment of Act 74, Mic	:n. P.A. 19	ZI DEC	94	8:24	4. M		7	75 TY	1A	
Wayne Loc	ated in:	Corner Code ##		FORES				LEH				
Dearborn Township #09	•			· 4492 3	· ₹	i sati Ari	Parasi Timber	in Atu ∖YTY:	月25日 株子日	J), TJF	nte	LVJ
4	2S_R_10E	E-13						with				
· ·	R		"					A. 199				
	R		-				٠. ـ	1.10	s.1 -	~ 7	11	
	R		-	APPR	OVE	ON:	<u> 1Z</u>	14/9	1-	rc	Z.	
	R		- [WAYN							N	
	R		-	J	PEER	GRO	JP C	OMMI	TEE			
	R		" .	,								
	R	***************************************	- I	Register	r of D	eeds	Star	np &	File	Nun	ıber	
· · · · · · · · · · · · · · · · · · ·			· L									
4. Lot No, Recorded Plat _												
5. Private Claims			· · · · · · · · · · · · · · · · · · ·	— A	В	C D	E	F G	н	l J	к	L
			-	2	_ <u> </u> _	LĮ.			١	ļļ		
				3	Ĭ	Ιĭ	Τ.	ì	1	Γí	\neg	- -
Lawrence R.									1			+
ı, Feindt , in a field surv	oven Octo	her 11	94	4	-7-	 8 -	 !	? 	·10—	╟╬	-	- 2
do hereby certily that under requirements of P.A	74 Michigan P.A.o.	1970 the corner points n	nontioned	5			+-			\vdash		
in lines 1 and 2 above were in conformance w	ith regulations and	rules therefore as requir	red in the	6 -	1 <mark>8</mark>	-17-	1	6	-15	—1 ¹ 4		-13-
 current manual of survey instructions of the Un 	ited States Departm	ent of the Interior Burea	But of Land	7		 -			4_	\sqcup		\perp
Management or by a decree of a Court of Law and	d/or that the corner	points mentioned in lines	3, 4 and 5	8	- (19	20-			-22	-23	l	24
above were in conformance with the rules of the Court of Law; established, re-established, n	Michigan Board of	Land Surveyors or by a Di	ecree of a	9	Ĩ	Ĭ		i I	Ï	Ĩ		
expressed below:	nonumentea, re-ma	numented, recovered,	lound as	10					\top			\top
				Ī	–30	29 1	2	B	27—	—26 I	-1-	-25— I
NOTE: Not more than 4 corners, all in the on this certificate.	e same town and	range, may be record	ded	11		-			-	┝		+
on this certificate.				12	-31	-32-	-3	3—	34	35	+	-36
A. Description of original monument and	accessories and/	or subsequent restora	tion:	13 L	_L	<u> </u>	Ф-1					
E-13) South Corner Commo	n to Secti	one 32 and 33	то	ев	10	_						
GENERAL LAND OFFICE	WAYNE COUNTY	BUREAU OF TAXATION	M. D. O.		10							
SET POST FOR CORNER	IRON		3/4" F	PIPE								
WHITE OAK 16"-324 W-22 LINKS(14.52') HICKORY 12"-NO5 E-32 LINKS(21.12')			N10 E-	35.70	'-CE1	ITER	OF M	ANHOL	E			
DECEMBER 16, 1816	SE'LY- 53.53' SW'LY- 99.68'		845 E-	32.00	114	CORN	ER O	CAT	CH E	ASI	и	
BY: JOSEPH FLETCHER, DS	NW'LY- 88.48'			- 53.65 IER 12,			WER	OLE				
,	NE'LY- 67.60'			HN STIII			VEV (CHICE				

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SSE'LY-74.20'-MANHOLE COVER

SW'LY -51.15'-CROSS IN CONCRETE NW'LY -40.25'-CROSS IN CONCRETE WEST -88.70'-MONUMENT BOX

E-13) South Corner Common to Sections 32 and 33, Found 3/4" pipe in monument box. Distance to D-13 measured 2645.48' (WPA = 2645.36' and MDOT = 2644.68'). Corner was confirmed from property irons found in "Dearborn-Telegraph-Townline-Subdivision" as recorded in Liber 48, Page 37; and "Pilgrim-Telegraph-Subdivision" as recorded in Liber 33, Page 19.



BY: JOHN STUBITS, SURVEY CHIEF

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

E-13) South Corner Common to Sections 32 and 33, T 2 S, R 10 E Found 3/4" pipe in monument box and placed Wayne County brass disk with license #21566 over pipe at the intersection of the North bound lane of Telegraph Road and Van Born Road. Road surface is asphalt. Corner is accepted as a careful and faithful reestablishment of the position of the original corner.

West - 88.81' - Found 1/2" iron rod in monument box at E-1 of T3S, R10E

S08°E - 53.55' - Found MDOT PK nail & cap in SW face of power pole N28°E - 57.92' - Found PK nail in South side of power pole

N56°W - 81.17' - Set WCR cap in South face of power pole

2R11 D-MISC

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

Signed by Lawrence R. E	Date:	12/21/94	
Surveyor's Michigan License No21566			•