LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Wexford (County)	Located In	Corner Code #		
Public Land Survey	T 22N R 9W	B12		
Property Controlling in Section	T R S T R			
Miscellaneous Property in Section	S		Register of Deeds Stam	p & File Number
4. Lot No:	Recorded Plat:		ABCDEFGH	I J K L M
5. Private Claims:			1	
requirements of PA 74, Mic and 2 above were in confor the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established,	eld survey on <u>January 11</u> , <u>2011</u> do here chigan PA of 1970, the corner points remance with regulations and rules there wey instructions of the United States nagement or by a decree of a Court of lines 3, 4 and 5 above were in conform Land Surveyors or by a Decree of monumented, recovered, found as exp. 2 corners, all in the same town a rtificate.	mentioned in lines 1 refore as required in Department of the Law and/or that the mance with the rules of a Court of Law; pressed below:	3 4	
A Description of original	monument and accessories and/o	or subsequent restoration	13	
(1) Tamarack 1 - 1908 – CSR – E Distance to Son to Ann Arbor R - 1971 – Certifica corner descriptic - 2000 – LCRC L of water in swar Teed). Distance Teed), distance Cap. This corne 2) 6" Dead Tam	A.J. Teed – Survey in Section 3 10" S86°W 8; D.E. Teed – Survey in Section 3 uth ¼ Corner 2640', distance to ailroad 1203.1'. Leeson Drain of the of Survey, L. 246, P. 693 – Monor witness given. Distance to . 5, P. 252 – C. Pullen, PS #390 mp. Stake is 20' East of the Lee to East ¼ Corner is 2648.62' (to North ¼ corner is 2640.90'. For is accepted as the best available arack N86°W 9.93', 3) 8" dead 630°W 35.85', 6) Center of Less	B1 for Leeson Drain. It is East 1/4 Corner 2652. description is 20' West M. McClung, PS #1305 to East 1/4 Corner 2652 095 – Found bottom 1 eson Drain. Found st 1/2652.3' – Teed), distanced wood stake able evidence of the pol Tamarack S48°E 11.	No Witnesses or description .3', Distance to West ¼ Cornst of and paralleling the North 37 – Survey in Section 31, L. 2.30', Distance to South ¼ C 12" of Teed's wooden stake is ump remains S86°W 5.3' (Stance to South ¼ corner is 26 with 1" x 72" iron pipe with V osition of the corner.	given for center. ler 2756.00', distance n-South 1/4 line. ler 251, P. 222. No orner 2639.38'. In muck and under 2' 86°W 5.33' – R. by 39.39' (2640' – Vexford County Brass 613°E 33.50'.
B. Description of corner	evidence found and/or method app	olied in restoring or re-es	stablishing corner:	
Grade – in mars	er sections 31, T22N, R9W - Fo sh per Pullen. Witnesses 1, 2 & nce of the position of the corner	& 3 are gone. 1 ½" Br	unty Brass Cap on rebar in 1 ass Cap monument accepte	l" pipe, 2' above d as the best
C. Description of monun	nent for corner and accessories est	tablished to perpetuate I	locating the position of the corne	er:
Add Blue Carse N48°E 44.48' to S13°E 33.55' to S30°W 35.78'	ounty Brass Cap on rebar in 1" onite Post 1' West o set ½" X 18" rebar o fd. 1" pipe under water (#4) to fd. 60d nail in E. side Fence to set ½" X 18" rebar		CERTE	RAIG W. MCVEAN OFESSIONAL UNVEYOR NO. 39088
Signed by: Surveyor's Michigan	License No.: 39088	lu Date:	8/24/2011	The second secon