

## RECEIVED

## LAND CORNER RECORDATION CERTIFICATE

C. A. A. Markey Services				NEUKIYED					
				1995	BEC LA	. Dit	O. ₽••		
JAN 1 7 1996 LAND CORNER RECORDATION CERTIFICATE				1000	DEC 11	FH.	٥: 5 <u> </u> ,	-Amı,	
	LAND CORN			1.	o La	û	. , iti	ECEIN	
For corners in CO	MMISSIOFiling Requir	rement of Act 74, Mich. P.A	L 1970	J. com.	or Low	5,546# <b>:</b> ₹	PA NE SEA	• • .	
Wexford	Located In:	Corner Code #		WE	(Foga)	ំនួចបុរ្តៅ	<b>.15, I.)E</b> (	0 4 1	
(County)		. 55,115, 5555 !!		č. r	All Coles				
						1.0	2	Loca ga	
1. Public Land Survey	T 22N R 10V	<i>M</i> <u>M−5</u>					WEXEC	oro occ	
•	TR						REGI	STEP OF	
	T R								
	ĩ R								
2. Property Controlling	S T R								
in Section	S T R								
3. Miscellaneous	S T R					•			
Property in Section	S T R		Register	of Deeds	Stamp	& File N	lumber	ì	
		-				<del></del>			
			A	8 C	DEF	а н	1 J K	i L M	
5. Private Claims	<u> </u>								
			2	-6	1	3	-3-1	-1-	
			3	<del>-}</del> -	<del>                                     </del>	<del>-}}-</del>	<del>                                     </del>		
Cookers D. Smith			4	-}	)	10	13	—12—	
George D: Smith, in a field survey on August 25, 19, 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned						<del>- - -</del>		•	
do hereby certify that under re-	quirements of P.A. 74, Michigan P	'.A. of 1970, the comer points menti rules therefore as required in the cu	ioned 6	-181	716-	15-	,4	-13-	
		ment of the Interior, Bureau of							
Management or by a decree o	f a Court of Law and/or that the o	comer points mentioned in lines 3, 4	4 and 8	-192	0		-23	—24——	
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found									
Decree of a Court of Law; esta as expressed below:	ablished, re-established, monume	nted, re-monumented, recovered, for	ound 10	-302	9   128-	27-	26	—25—	
•			11	أ		_	L.ii l		
NOTE: Not more than 4 corners, all in the same town and range, may be recorded 4 on this certificate.									
on this certificate.			12	31 3	2 33-	<del>-1</del> 34	35	-36  1	
A Description of original	monument and accessories	and/or subsequent restoration:	· 13L		1 1				
1837 GLO Quarter Se	ection post by John Brink, Den	uty Surveyor, Hemlock 28 S12°	, W.68 Sugar N	. 67° W 1	12				
1853 GLO Subdivision	on of Sec. 7 & 18, T22N, R9W	by V.W. Caukin Deputy Surveyo	or. Beech 16 N	18°F 29	Sugar 1	4 5 779	721		
1881 A.J. Teed Surve	y in Sec. 7, T22N, R9W (Liber	1, Page 126) Corner found no d	escription or wi	inesses o	iven	7077	, 21		
1891 A.J. Teed Surve	y, Liber I, Page 140, found old	stake, Hemlock 36 S 48½° W 57	7		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				
1895 A. J. Teed Surve	ey, Liber I, Page 182, stone wit	th "x" in top, no witnesses given							
1898 A.J. Teed Surve	y for Petition, Liber 1, Page 18	0, found stake and stones.							
1907 D.E. Teed Surv	ey in Sec. 7, T22N, R9W, Lib	er 1, Page 125, found stone, fenc	e post N 52° E	60, F.P.	N 431/2°	W 511/2	. FP		
S 42° W 641/2		•		-			•		
"A" CONTINUED O	N BACK								
3. Description of corner	evidence found and/or metho	od applied in restoring or reesta	ahlishing come	<b>,</b>					
			Lange and a course	••					
			¥.	-					

Found 5/8 iron ± 1.8' West of centerline North-South Road and ± 6'N of centerline gravel road West and opposite centerline road East extended. This corner is accepted as a careful and faithful perpetuation of the position of the original corner, being the Section corner common to sections 12 & 13, T22N, R10W and Sections 7 & 18, T22N, R9W.

> Peer Group Reviewed and Approved Richard D. Wilcox, Wexford County Surveyor

C. Description of monument for comer and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron with Wexford County Brass Cap stamped SE 12 1995 PS 39098 S 65° W 43.04' Twin 10" Walnut N 48° W 43.12' 12" W. Pine

N 18° W 67.46' 30" Maple

N 74° E 38.05 ' corner fence post (nail North Side)

AOFESSION SMITH PROFESSIONAL

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

## A Continued:

1907 Devoe Survey found stone, Liber 1, Page 141 no witnesses given

1980 Erickson, PS# 16929, Certificate of Survey, Liber 2, Pages 60-61 found iron in intersection 1' West of Bit. centerline N-S, N. Edge of gravel road E-W S 50° W 10" Ch. Elm 43.17', N 43° W 22" Maple 66.55', N 45° W 6" Pine 43.00' N 65° W 6 " Pine 55.14'.

1980 Erickson, PS# 16929, L.C.R.C. Liber 3, Page 321, found iron in bituminous.

1994 Finnerty, PS# 16038, Certificate of Survey, Liber 73, Page 346, Corner found no description given.