LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY ____	T. 24 N. S., R. 10 E. W.	D-10
2. PROPERTY CONTROLLING IN SECTION 29	,T. 24 N. S., R. 10 E. W.	6; 9; 12; 13
3. MISCELLANEOUS PROPERTY IN SECTION ____	,T. ____ N. S., R. ____ E. W.	

4. LOT NO. ____ , RECORDED PLAT ____

5. PRIVATE CLAIMS ____

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on Sept. 27, 1978, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on ____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

C. (continued)

12

Set 5/8"X40"re-rod w/plastic RLS Cap & Ced.Post w/Loc. Tag

12" Cherry (clump)	N72°W	48.7
9" W.Pine	S36°E	102.7
15" Maple	S82°E	77.6
Fd. Conc. Mon.	N83°42'E	3.46
E-W trail rd.	Due S.	100'±

13

Set 5/8"X40" re-rod w/plastic Cap
Set Ced. post w/Loc. Tag.

8" Cedar	S56°E	15.1
12" Cedar	N26°E	4.1
12" Cedar	S14°E	3.8
Fd. Conc. Mon.	N76°33'E	1.42

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

D-10 Established Ctr. of Sec.29 at intersection of 1/4 lines.

6 Established Ctr. of NE 1/4 per standard B.L.M. instructions.

9 Established 1/8 Cor. per standard B.L.M. instructions.

12 Established 1/8 Cor. per standard B.L.M. Instructions.

13 Established Ctr. of SE 1/4 per standard B.L.M. instructions.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-10

Set 5/8"X40" re-rod w/plastic RLS Cap.&Ced.Post w/Loc.Tag.

7" R.Pine	N88°W	5.3
9" R.Pine	S11°E	14.2
14" W.Pine	N32°E	9.6
Fd. Conc. Mon.	N88°56'E	6.97

6

Set 5/8"X40" Re-rod w/RLS Cap & Ced.Post w/Loc. Tag

4" Tw. W.Pine	N39°W	85.3
5" W.Pine	S76°W	57.5
11" Tw. Cherry	S26°W	21.2
Fd. Conc.Mon.	S77°49'E	8.08
N-S trail rd.	Due W.	110'±

9

Set 5/8"X40"re-rod w/plastic Cap &Set Ced.Post w/Loc.Tag.

8" Maple	S46°E	33.7
6" R.Pine	S70°W	7.2
5" Maple	N54°E	8.9
Fd. Conc. Mon.	S85°27'E	3.86

SIGNED BY Carl F. Roser 10-2-78 DATE ____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

STATE OF MICHIGAN (SEAL) CARL F. ROSER LAND SURVEYOR NO. 12028 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY ____ DATE ____
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY ____ DATE ____
MICHIGAN REGISTERED LAND SURVEYOR

GREENWOOD TOWNSHIP
WEXFORD COUNTY

SURVEYOR'S MICHIGAN REGISTRATION NO. ____

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET