

L.9, P.61

1/16/2020

Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Craig W. McVean

Field Survey Date: Aug. 14, 2019

For corner(s) in: Wexford County

Original Public Land Survey Corner

Corner Code

S	T	R	
S	T	R	
S	T	R	
S	T	R	

Property Controlling Corner

Corner Code

S	T	R	
S	T	R	
S	T	R	
S	T	R	

Property Corner

Corner Code

S	20	T	24N	R	10W	9
S	20	T	24N	R	10W	16
S		T		R		
S		T		R		

Protracted Public Land Survey Corner

Corner Code

S	T	R	
S	T	R	
S	T	R	
S	T	R	

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner History

9 – CE 1/16 Sec. 20, T24N, R10W
- None

16 – E 1/16 Corner common to Sec. 20 & 29,
T24N, R10W
- **1962** – K. J. Ostling (PS # 10068)
Set 1" x 24" pipe midpoint on-line between section
and ¼ corners.
1) 7" R. Oak N80½°W 91.7'
2) 5" Maple N78½°E 36.6'
- **1978** – LCRC L. 3, p. 186 – C. F. Roser
(PS # 12028)
Fd. 1" pipe & Ced. Post
1) 10" Twin R. Oak N74°W 91.4'
2) 9" Maple N82°E 36.4'
3) 11" Maple S44°E 52.4'
N-S Trail Rd. Due W. 170'±

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

9 – CE 1/16 Corner Sec. 20, T24N, R10W
Set 2" Aluminum Cap on 5/8" x 34" long iron rebar
per Standard BLM procedure.

16 – E. 1/16 Corner common to Sec. 20 & 29,
T24N, R10W.
Found 1" I. D. iron pipe per Ostling and Roser.
Condition of witnesses: #1 – Dead snag;
#2 & 3 – OK. 1" pipe accepted as the best
available evidence of the position of the corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner


9 – CE 1/16 Corner Sec. 20, T24N, R10W
Stamped 2" Aluminum Cap on 5/8" x 34" long iron
rebar. Set Blue Composite Post with loc. tag 1' NW.
N3°W 26.40' to set N & T in W. side 13" Oak
N60°E 26.49' to set N & T in SE side Tw. 6" W. Pine
S60°E 16.80' to set N & T in SW side 3" W. Pine
S62°W 40.42' to set N & T in SE side 10" Oak

16 – E 1/16 Corner common to Sec. 20 & 29,
T24N, R10W
Drove stamped 2" Aluminum Cap on 5/8" x 24" long
iron rebar into center of found 1" iron pipe.
WNW 0.5' to Face Cedar post with Loc. Tag.
S35°W 9.87' to set N & T in SE side 3" Red Pine
N29°W 9.15' to set N & T in SW side 10" Oak
S50°E 52.97' to set N & T in NE side
18" Red Maple (#3)
N75°E 36.66' to set N & T in S. side 17" Red
Maple (#2)





Craig W. McVean



Date

Professional Surveyor's License No.: 39088

Prepared By:

Craig W. McVean

Michigan Dept. of Natural Resources

8015 Mackinaw Trail

Cadillac, Michigan 49601