

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Wexford
(County)

Located In

Corner Code #

1. Public Land Survey
T _____ R _____
T _____ R _____
2. Property Controlling
in Section S 34 T 24N R 10W 1
S _____ T _____ R _____
3. Miscellaneous
Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on July 27, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1 - None

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

1 - W 1/16 Corner common to Section 27 & 34, T24N, R10W - Set 2" Alum. Cap on 5/8" x 34" rebar per Standard BLM procedure. Centerline of E-W gravel road is 5' South. East 18'± to fence to North. East 28'± to down fence remains to South.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1 - Stamped 2" Alum. Cap on 5/8" x 34" long iron rebar.
South 33.00' to set 2" Alum. Cap on 5/8" x 34" rebar on line and add cedar post with loc. tag.
S36°E 43.86' to set N & T in SW side 12" Sugar Maple
S15°E 71.18' to set N & T in E. side Tw. 9" Sugar Maple
S50°W 52.79' to set N & T in SE side 5" Sugar Maple
N35°W 25.01' to set N & T in SW side 12" Sugar Maple



Signed by:

Craig W. McVean

Date:

11/22/2010

Surveyor's Michigan License No.:

39088