

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Wexford  
(County)

Located In

Corner Code #

1. Public Land Survey T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling  
in Section S 1 T 24N R 11W 8  
S 4 T 24N R 11W SS 1/64
3. Miscellaneous  
Property in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Craig W. McVean, in a field survey on May 24, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

8 - None

SS 1/64 - None

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

8 - CW 1/16 Corner Sec. 1 - Set 2" Alum. Cap on 5/8" x 24" rebar per standard BLM procedure. N-S down fence is 16.5' E.

SS 1/64 - corner common to Section 3 & 4, T24N, R11W - being the SE Corner of the N 1/2 of the SE 1/4 of the SE 1/4, Sec. 4 - Set 2" Alum. Cap on 5/8" x 34" rebar per standard BLM procedure. N-S fence remains are 8'± West. Centerline of N-S 2-track is 22' West.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8 - Stamped 2" Alum. Cap on 5/8" x 34" long iron rebar  
Set Blue Carsonite Post with loc. tag 1' NE  
N8°E 14.74' to set N & T in W. side 5" S. Maple  
S60°W 21.58' to set N & T in SE side 11" S. Maple  
S37°E 30.30' to set N & T in NE side Tw. 5" and 10" S. Maple  
S87°E 28.20' to set N & T in N. side 12" B. Cherry

SS 1/64 - Stamped 2" Alum. Cap on 5/8" x 34" long iron rebar.  
Set Blue Carsonite Post with loc. tag 1' NW  
N52°E 25.40' to set N & T in W side 8" R. Pine  
S14°W 33.61' to set N & T in W. side 4" Cherry  
N85°W 43.14' to set N & T in N. side 11" R. Pine  
N19°W 92.04' to set N & T in E. side 13" R. Pine

Signed by:

Craig W. McVean

Date:

11/19/2012

Surveyor's Michigan License No.:

39088

