

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Wexford
(County)

Located In

Corner Code #

1. Public Land Survey T _____ R _____
T _____ R _____
2. Property Controlling in Section S 2 T 24N R 11W 13
S 2 T 24N R 11W 14
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on May 25, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

13 - None

14 - 1974 - LCRC - L. 2, p. 688 - C. F. Roser - set 1" x 36" pipe and Cedar post with loc. tag per Standard BLM instructions. N-S Fence due E. 4'; Fn. to West Due N 27';
1) 8" Maple N37°W 3.90'; 2) 8" Maple S82°W 29.70';
3) 12" Cherry S25°E 28.93'

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

13 - SE 1/16 Corner Sec. 2, T24N, R11W - Set 2" Alum. Cap on 5/8" x 34" iron rebar per Standard BLM procedure.

14 - S 1/16 Corner common to Sections 1 & 2, T24N, R11W - Set 2" Alum. Cap on 5/8" x 34" iron rebar per Standard BLM procedure.

- Reference Pt. 'L' - Fd. 1" I.D. iron pipe per C. F. Roser is S4°56'E 3.59' from 'L-4'. Could not accept 1" pipe since it is based on a rejected position at 'K2'. 1" iron pipe not utilized as corner '14' in this survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

13 - Stamped 2" Alum. Cap on 5/8" x 34" iron rebar
Set Blue Carsonite Post with loc. tag 1' NW
N71°W 31.45' to set N & T in N. side 14" S. Maple Clp. - 4.
N25°W 15.56' to set N & T in E. side 11" B. Cherry
N31°E 10.49' to set N & T in NW side 4" Ironwood
S5°W 46.36' to set N & T in W. side Twin 15" S. Maple

14 - Stamped 2" Alum. Cap on 5/8" x 34" iron rebar
Set Blue Carsonite post with loc. tag 1' NW
S72°W 1.91' to Fd. 60d nail and tag in face of 12" S. Maple
S23°E 32.41' to set N & T at Fd. Nail in W. side 14" Cherry
N45°W 8.80' to set N & T in SW side Twin 15" S. Maple
S4°56'E 3.59' to Ref. Pt. 'L' - 1" pipe

Signed by:

Craig W. McVean

Date:

11/19/2012

Surveyor's Michigan License No.:

39088

