
## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970 Located In Corner Code # Т Register of Deeds Stamp & File Number Recorded Plat:

I, <u>Craig W McVean</u>, in a field survey on <u>Sept. 15</u>, 20<u>15</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

NS 1/64 Corner Sec. 28 & 29 - None

For Corners In: Wexford

in Section

3. Miscellaneous Property in Section

5. Private Claims:

4. Lot No:

1. Public Land Survey

2. Property Controlling

(County)

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

NS 1/64 Corner - common to Section 28 & 29, T24N, R11W - being the NW corner of the S 1/2 of the NW 1/4 of the SW 1/4 Sec. 28 -Set Stamped 2" Aluminum Cap on 5/8" x 34" rebar per Standard BLM procedure in lowland area.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

N10°E 4.35' to set N & T in E. side 8" Willow S42°E 44.93' to set N & T in SW side 8" Elm N64°W 73.51' to set N & T in S, side 10" Elm N40°W 47.59' to set N & T in NE side 8" R. Maple

MICHIGA CRAIG W. MCVEAN ROFESSIONAL SURVEYOR No. 39088 A OPESSION 20/2016

Surveyor's Michigan License No.:

39088

Date: