LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Wexford

Wexford	Located In	Corner Code #	4 × 3 +
(County)			
1. Public Land Survey	T 24N R 11W T 24N R 10W	M1 A1	
2. Property Controlling in Section S	T R	131	7 8
3. Miscellaneous Property in Section S S S	T R T R T R		M re
4. Lot No: Reco	orded Plat:		Register of Deeds Stamp & File Number
5. Private Claims:			A B C D E F G H I J K L M
I, Craig W. McVean, in a field sur requirements of PA 74, Michigan I and 2 above were in conformance the current manual of survey ins Interior, Bureau of Land Manageme corner points mentioned in lines 3, of the Michigan Board of Land established, re-established, monun	PA of 1970, the corner points with regulations and rules the tructions of the United States and or by a decree of a Court of 4 and 5 above were in confor Surveyors or by a Decree	mentioned in lines 1 erefore as required in s Department of the of Law and/or that the mance with the rules of a Court of Law:	2 6 5 4 3 2 1 1 3 4 7 8 9 10 11 12 12 15 16 18 17 15 14 13 17 18 19 20 21 22 23 24
NOTE: Not more than 2 corn be recorded on this certificat	ers, all in the same town a	and range, may	9 10 30 -29 -28 -27 -26 -25 - 11 12 -31 -32 -33 -34 -35 -36
A. Description of original monut	ment and accessories and/	or subsequent restoration	13
M1 & A1 – 1838 – Post set for township corner in original governmet survey by John Brink, Deputy Surveyor, Corner witnessed by: (1) Beech 10" N76°E 32 links; (2) Beech 11 S17°E 15 links - 1909 – Survey of section 6, Wells & Higman Co., Town 24 North, Range 10 West, by E. P. Waterman – Old Stake at Cor. #18 – Hem. Stake 2" x 2"; (3) Hemlock 24" S17 3/4°E 14.7' - 1913 – CSR L. 2, p. 452 – Grand Traverse Co. Records (GTCR) – Survey of section 31, Town 24 North, Range 10 West, by E. P. Waterman "Old stake and old wit." - 1937 – Misc. DNR notes of survey line run along North line of Townships T24N, R11 & 10W. The names F. L. VanSickle, Rathburn & F. Clark appear on various pages of the notes. The survey lines may have been assisted by CCC crews. It appears M. Schaaf used this survey line to search for corner evidence in the 1940's. – "East random N. side Sec. 1 – 81.59 – Intersect line 1 ch 80 lks. South on N & S random East side Sec. 1." Notes for Section 6, T24N, R10W, 72.40 chains West of NE cor. of Section 6, "fences North and East". - 1942 – M. Schaaf – At 80.42 fr. West and 124 S. of post: Fr. East at 73.09 and 73 N. of post. SE site and NE stp. exact. NBT's; (4) WP Stp. 20" N40°E 59'; (5) WP Stp. 40" S64°E 78; (6) WP Stp. 34" S26½°W 75; (7) WP Stp. 32" N52°W 95. Just 51 lks. S. of furrow cor. Hem. LT with def. site at 57.78 and 119 N. - 1970 – C. Roser – LCRC L. 3, p. 78 (1977) "Set Std. Dept. Mon. on prolongation of a line thru the N ¼ and NE Cor. of Section 6 and in line with old fence to N. This fits Waterman survey of Sec. 6 & Sec. 31." (8) 5" Maple in group of 2 – N64°E 32.8'; (9) 10" Maple in group of 3 – S72°E 33.9'. Fence Cor. with fn. remains N & E – Due N. 24.5' - 2008 – LCRC #2008L-00017 – R. F. Mitchell - Grand Traverse Co. Records. Found DNR monument as recorded by Roser in 1974. This position is consistent with the Waterman corner positon and is accepted as a careful and faithful re-establishment of the original GLO corner location by Roser in 1974. Replaced DNR monument with a 2½" by 30"			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: M1 & A1 – Township Corner common to Section 1, T24N, R11W; Section 6, T24N, R10W; Section 36, T25N, R11W and Section 31, T25N, R10W – Found 3 ¼" Brass Cap Monument per LCRC #2008L-00017 per R. F. Mitchell. Corner of fence remains N, E & W is 25' North. No evidence of witnesses #1, 2 or 3. Brass Cap monument fits Waterman's distances N, S & E fairly well. 3 ¼" Brass cap monument accepted as the best available evidence of the position of the original corner.			
 Reference Point 'J' – S80°25'W 47.67' from 'M1 & A1' found wood stake remains that agrees with Schaaf's 4 BTs. Set Spike at base of stake. The evidence used by Schaaf to establish this position seems suspect and doesn't agree with historical survey by Waterman or occupation in area. Stake per M. Schaaf not utilized 'M1 & A1' in this survey. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 			
M1 & A1 – 31/4" 'Grand Traverse N62°E 33.06' to fd. 6 S71°E 34.15' to fd. 6 S5°E 51.44' to fd. 60 S54°W 45.59' to fd. Set Blue Carsonite F	e County Remonumentation 60d nail in N. side Twin 9" F 60d nail in N. side Twin 12" 70d nail in E. side 10" Red P 60d nail in NW side 10" Re Post 1' North Reference Point 'J' – Spike	n' Brass Cap on 2½" x 30' Red Maple(#8) & 15" Red Maple (#9) ine (#10) d Pine (#11)	
	F	ORM APPROVED BY MICHIGA	N STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971 Revised May 14, 1975 Revised Jan. 1983 Revised Oct. 1995