

**SURVEY & REMONUMENTATION**

MAR 09 1998

RECORDED  
WASHTENAW COUNTY, MI

JAN 22 8 31 AM '98

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

PEGGY A. HAINES  
COUNTY CLERK/REGISTER

For corners in

WASHTENAW (County)	Located In:	Corner Code #
1. Public Land Survey PITTSFIELD	T <u>3S</u> R <u>6E</u>	<u>G-13</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

- COPY -

- COPY -

Liber **00002** Page **0049** RM  
Register of Deeds Stamp & File Number

I, LORI E. BEYER, in a field survey on NOVEMBER 26, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate

	A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. - 1819 FIELD NOTES  
SET WOOD POST  
20" W.O. N 81° W 36.3'  
20" LYNN S 27° W 53.5'

Continued on Back.



B. Description of corner evidence and/or method applied in restoring or reestablishing corner:

FOUND 3/4" IRON PIPE WITH W.C.R.C. CAP #13028 INSIDE MONUMENT BOX AT PAVEMENT SURFACE. BASED ON NOTES BY R. CAMPBELL AND FOUND WITNESSES, ACCEPTED THIS MONUMENT AS THE CORNER.  
PLEASE NOTE: THE WITNESSES AS LISTED BY FAHRNER AND OLIVER APPEAR TO BE FOR A DIFFERENT CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

FOUND 3/4" IRON PIPE WITH W.C.R.C. CAP #13028 INSIDE MONUMENT BOX AT PAVEMENT SURFACE. SET ALUMINUM REMONUMENTATION CAP STAMPED 'ALNM - #41092' OVER FOUND IRON PIPE.

- (2) 23" HICKORY S 31° E 36.05' FD NAIL E. SIDE
- (4) 23" STUMP N 22° W 42.5' CENTER
- (9) POWER POLE N 74° E 78.18' FD NAIL S. SIDE
- (11) POWER POLE N 56° W 122.11' FD BOAT SPIKE E. SIDE
- (12) 6" PINE S 41° W 37.0'

APPROVED  
DATE 12/2/97  
CO. REP. KA

I BELIEVE THAT THIS POINT SHOULD BE ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

Signed by Lori E. Beyer  
Surveyor's Michigan License No. 41092

Date Dec 8, 1997

— COPY —

Paragraph A Continued:

R. Barnes, W.C. Lowe — November 1932  
 Washtenaw Co. Road Commission — Grid Book

Found State Monument

(1) 9" HICKORY	N 31° E	64.05'
(2) 20" HICKORY	S 23° E	36.03'
(3) 22" HICKORY	S 53° W	61.1'
(4) 12" HICKORY	N 47° W	42.8'

Norman N. Fahrner, RLS #17620 — March 1972

Washtenaw Co. Records — LCRC L. 1 Pg. 693, P.A. 132 Certificates, L. 1412 Pg. 480, L. 1395 Pg. 513

Found 4" Steel Monument raised to road surface with 3/4" Iron Pipe. No witnesses remaining.

(5) POWER POLE	N 34° W	39.3'
(6) 24" HICKORY	N 79° W	209.5'
(7) POWER POLE	N 77° E	106.7'
(8) TELEPHONE POLE	S 66° W	66.8'

\*(THESE WITNESSES MAY BE FOR A DIFFERENT CORNER)

William J. Robey, RLS #20711 — September 1973

Washtenaw Co. Records — P.A. 132 Certificate, L. 1470 Pg. 53, L. 1470 Pg. 52, L. 1532 Pg. 520

Found Monument. No witnesses given.

John F. Oliver, RLS #19840 — April 1972

Washtenaw Co. Records — P.A. 132 Certificate L. 1461 Pg. 744

Found 4" Steel Monument

(5) POWER POLE	N 34° W	39.3'
(6) 24" HICKORY	N 79° W	209.5'
(7) POWER POLE	N 77° E	106.7'
(8) TELEPHONE POLE	S 66° W	66.8'

\*(THESE WITNESSES MAY BE FOR A DIFFERENT CORNER)

John Litchfield Snyder, RLS #13352 — December 1977

Washtenaw Co. Records — P.A. 132 Certificates, L. 1629 Pg. 699, L. 1597 Pg. 927, L. 1596 Pg. 220

L. 1598 Pg. 294

Found 1 1/2" Iron Pipe

(1) 12" HICKORY	N 31° E	64.35'
(2) 20" HICKORY	S 23° E	35.8'
(4) 16" HICKORY	N 20° W	42.4'

Robert A. Campbell, RLS #13028 — November 1982

Washtenaw Co. Records — LCRC L. 6 Pg. 261

Found 1/2" Iron Pipe over 4" Monument reset at road surface 3/4"x16" Iron Pipe in Mon. box over 4" Monument

(2) 23" HICKORY	S 32° E	36.00' FND NAIL E.SIDE
(4) 20" HICKORY	N 25° W	42.89' FND NAIL NE.SIDE
(9) POWER POLE	N 72° E	78.18' SET NAIL IN S.SIDE
(10) TELEPHONE POLE	S 15° W	31.10' FND NAIL IN E.SIDE

\*(Comment from field notes: Witnesses from L. 1 Pg. 693 may be for a different corner)