

2001 Alpena County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Alpena

(County)

Located in:

Corner Code #

1. Public Land Survey

X T30N R 07E
T30N R 08E

M-8
A-8 ✓

2. Property Controlling
In Section

S T R
S T R

3. Miscellaneous
Property In Sec.

S T R
S T R

FEB. 01 2002

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Wayne T. Lewis, in a field survey on 2-24-01, 19X do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1839: Lewis Clason set post and witnessed
1908: Unknown surveyor for Alpena Co. Road Commission, witnessed corner
1930-1950: Marcus Schaff, P.S., set iron, no witnesses given
1973: Alpena Co. Road Commission found gas pipe & set 1/2" iron and witnessed
1999: Alpena Co. Road Commission, found 1/2" rod, and witnessed

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" rod in mon. box in c/l of Spruce Road N/S and c/l of fire trail E/W

This corner is accepted as the best evidence of the location of the original corner.


P.A. 345 ALPENA COUNTY
PEER APPROVED 08-06-01
N.T.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

2001: Placed 3" Alpena County Remonumentation Cap, stamped to identify the corner, on exist. 1/2" rod in mon. box

Witnesses:

N 50° E 81.39' 24" White Pine (set tag #41922)
S 50° E 65.03' 8" White Pine (set tag #41922 over disk and nail)
S 50° W 74.35' 21" White Pine (set tag #41922 over disk and nail)
N 70° W 72.74' 6" White Pine (set tag #41922 over disk and nail)



Signed by [Signature]

Date September 14, 2001

Surveyor's Michigan License No. 41922

L-2 P-370
09/18/2001 08:54A
Page: 1 of 1
Kathy J. Matash, Register Alpena Co., MI LDC 9.00

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN. 1983
REVISED OCT., 1998