

Received  
01-09-2015 09:11 am.

**LAND CORNER RECORDATION CERTIFICATE**

Filing Requirement of Act 74, Mich. P.A. 1970 as Amended  
For corners in

<u>Presque Isle</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>33N</u> R <u>5E</u>	<u>1-9</u>
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

Instrument 201500000114 OR  
Liber Page 558 981

201500000114  
Filed for Record in  
PRESQUE ISLE COUNTY  
CATHY I. IDALSKI, REG OF DEEDS  
01-09-2015 At 09:21 am.  
LC-REMON 17.00  
OR Liber 558 Page 981 - 982


Register of Deeds Stamp & Figure Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Travis L. Horrocks, in a field survey on June 30, 20 14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

L-9  
SEE BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-9  
1/2" ROD & CAP #15410  
S 30° E 11.66' 10" BALSAM #15410  
S 72° W 20.87' 8" ASH #15410  
N 82° W 28.34' 14" MAPLE W/BLAZE TAG OVERGROWN  
N 18° W 31.74' 8" BALSAM #15410  
N 10° E 20.94' STUMP



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-9  
1/2" ROD & REMON CAP #59298  
S 30° E 11.68' 10" BALSAM #15410 (OW)  
S 72° W 20.87' 8" ASH #15410 (OW)  
N 82° W 28.34' 14" MAPLE (OW) #59298  
N 18° W 31.74' 8" BALSAM #15410 (OW)  
N 10° W 20.92' STUMP (OW)

Retified by Peer Group  
in accordance with P.A. 345  
Chairman Arthur J. Chan  
Date 11-4-2014

Signed by [Signature]  
Surveyor's Michigan License No. 59298

WITNESS TAGS & NAILS USED

Date 11/04/14