

MAY 15 2007

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Located in:

Montmorency
(County)Vienna
(Township)

Corner Code #

1. Public Land Survey

T 31 N R 1-EK-132. Property Controlling
in SectionS T R 3. Miscellaneous
Property in Sec.S T R 4. Lot No. , Recorded Plat 5. Private Claims

I, Larry G. Beauregard in a field survey on May 2006, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

K-13: Section corner common to Sec's. 35 & 36, T 31 N, R 1 E.

1840 Lewis Clason D. S. set Sec. post, for Sec. 35 & 36. Wit's. mkd (1) Hem. 22" N42°W 7 L. (4.62') (2) Beech 24" N33°E 2 L. (1.32)

Aug. 1989 Donald E. Marlatt P.S. #18660 set mon. while traversing the 3rd. correction. Prepared Act 132 (Not recorded) Wit's. mkd. (3) N50°E 6" Cherry 43' (4) S85°W 25" Maple 126.2' (5) S85°E 6" Maple (Clump) 102.25', Fe. Line 2.5' South.

Oct. 1990 Donald E. Marlatt P.S. # 18660 fd. mon. Filed LCRC Rec. L. 1, P. 450. same wit's as above.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2												
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

K-13: May, 2006. Fd. conc. mon. by Marlatt in good condition & wit's. (4 & 5). (Ex. spike in tree), wit. #3 down & dead.

Placed 4" aluminum Co. Re-mon cap on top.

Accepted & approved by the peer group on 8-11-06 as a careful & faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13: 4" x 36" concrete monument with 4" aluminum County Re-mon cap on top.

Wit's. mkd. S80°E 102.33' 6" Maple in clump of (3) @ Note: This corner is on the twp. & 3rd. correction line 1645.97' East of the closing corner for Sec. 1 & 2, T30N, R1E, according to survey by Marlatt in 1989.
 West 126.14' 36" " @
 N60°E 61.65' 6" Cherry
 S18°E 17.25' 5" Tw. Cherry
 South 2.50' Old Fe. Line E & W.

Placed 60 d spike & P.S. tag # 18654 in trees. (Typ.)

Signed by Larry G. BeauregardDate Aug. 18, 2006Surveyor's Michigan License No. 18654

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971
 REVISED MAY 14, 1973
 REVISED JAN. 1983
 REVISED OCT. 1985

MONTMORENCY COUNTY REMONUMENTATION

APPROVED BY
PEER GROUP11-06
L.S.B.B
W