

## 1993 Alcona County Remonumentation Corner



001 PAGE 19

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Alcona

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 27N R 8E

M-8

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

RECORDED

Remon 1 Page 19

Dec 20 1 15 PM '93

*David A. Guthrie*REGISTER OF DEEDS  
ALCONA COUNTY, MICHIGAN

Register of Deeds Stamp &amp; File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

David B. Guthrie in a field survey on August 20, 19 93

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1838 - G.L.O. Survey by Lewis Clason - Set post and referenced S. Maple 7 - S27°W - 19 / W. Pine 30 - N54°W - 29

1903 - County Survey by Edward Chappelle - Referenced and set corner, W. Pine stump 36 - N51°W - 59 / W Pine stump 36 - N12°W - 130

1974 - Survey by James L. Scott, Found nail in North, South road and fenceline East intersection.

1977 - Survey by David B. Guthrie, Found nail in road centerline.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993: Found 1/2" Iron Rod at the intersection of the center of F-41 and a fenceline West.

SURVEY &  
REMONUMENTATION

1993

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: Set 1/2" X 24" Iron Rod with 3" brass cap stamped to identify the corner referenced:  
S78°W - Fence Corner Post - 35.32 Feet  
N80°W - Fence Post - 38.88 Feet  
N20°W - Utility Pole - 142.77 Feet  
S29°W - 18" Maple - 132.21

Signed by

*David B. Guthrie*

Date

12-2

Surveyor's Michigan License No. 22435

