

SURVEY & REMONUMENTATION

FEB 17 1994

001 PAGE 56

1993 ALCONA COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Alcona County
Remonumentation
Liber 1 Page 56

For corners in

Alcona

(County)

Located In:

Corner Code #

1. Public Land Survey

T _____ R _____

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S 24 T 27N R 9E

S _____ T _____ R _____

3. Miscellaneous
Property in Sec.

S _____ T _____ R _____

S _____ T _____ R _____

Other #6

L8 - 0.7 - M8

RECORDED

DEC 30 1 26 PM '93

Doris A. Bantline
REGISTER OF DEEDS
ALCONA COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, Duane R. MacNeill, in a field survey on December 14, 19 93

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1840 - Corner not set by G.L.O. Surveyor.

Corner has not been established on previous recorded or unrecorded surveys.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The corner was established by mathematically extending the E-W 1/4 line through the center of Section until it intersected a meander line as established by Duane R. MacNeill, R.L.S. from a previous survey in said Section 24 and a 1/2" re-rod was set at that location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Alcona County Remonumentation Aluminum Cap, appropriately stamped, secured to 1/2" re-rod.

Witnesses:

N 45° W 47.33 10" Spruce
N 85° W 23.70 18" W. Pine
S 40° W 22.42 14" R. Pine
S 15° E 80.82 8" Cedar

Witnesses were duplex nails bearing a plastic cap stamped License #19237.

Signed by

Duane R. MacNeill

Date December 29, 1993

Surveyor's Michigan License No. 19237