

FEB 17 1994

COMMISSION

001 PAGE 58

1993 ALCONA COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Alcona County
Remonumentation
Liber 1 Page 58

For corners in

Alcona

(County)

Located In:

Corner Code ##

RECORDED

1. Public Land Survey

T _____ R _____

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S 24 T 27N R 9E

S _____ T _____ R _____

3. Miscellaneous
Property in Sec.

S _____ T _____ R _____

S _____ T _____ R _____

Section #7

L - 8

DEC 30 1 27 PM '93

Doris A. Gauthier
REGISTER OF DEEDS
ALCONA COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Duane R. MacNeill, in a field survey on December 14, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1840 - Not set by G.L.O.
Surveyor.

1978 - Found 3/4" pipe by
John Oliver, R.L.S.

1981 - Found 3/4" pipe by
Nicholas B. DeYoung
R.L.S.

No Witnesses

No Witnesses

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Found 3/4" pipe and
drove 1/2" re-rod inside
of pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Alcona County Remonumentation Aluminum Cap, appropriately stamped, secured to 1/2" re-rod.

Witnesses:

Due East 7.30 8" Cedar
N 15° E 30.36 5" Cedar
S 55° W 14.57 8" Cedar
N 55° W 12.83 8" Cedar

Witnesses were set using duplex nails bearing
a plastic cap stamped License #19237.

Signed by

Duane R. MacNeill

Date December 29, 1993

Surveyor's Michigan License No. 19237