

1993 Alcona County Remonumentation Corner

001 PAGE 09

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

or corners in

Alcona
(County)

Located In:

Corner Code 77

Remon 1 Page 9

Dec 20 1 17 PM '93

David A. Guthrie
REGISTER OF DEEDS
ALCONA COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

Public Land Survey T 28 / NR 7E M-3
T _____ R _____
T _____ R _____
T _____ R _____
Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

Lot No. _____, Recorded Plat _____
Private Claims _____

David B. Guthrie a field survey on September 30, 19 93,
to hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

1. Description of original monument and accessories and/or subsequent restoration:

1839: G.L.O. Survey by Lewis Clason - Set post and referenced
Tam. 11 - N60°W - 15 / Tam. 16 - S32°W - 18

1987: Survey by David B. Guthrie - Found squared wood stake, set
1/2" Iron Rod adjacent and referenced.

1988: Survey by David B. Guthrie - Found squared wood stake and 1/2"
Iron Rod, Confirmed prior references.

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993: Found squared wood stake and 1/2" Iron Rod adjacent.

SURVEY &
REMONUMENTATION

1993

COMMISSION

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993: Set 1/2" X 24" Iron Rod with 3" aluminum cap stamped to
identify the corner. Referenced -
S72°W - 14" Cedar - 2.35 Feet
N39°W - 14" Cedar - 2.44 Feet
N21°E - 10" Cedar - 12.13 Feet
N74°W - 10" Cedar - 10.65 Feet
N12°W - 10" Cedar - 16.56 Feet



Signed by *David B. Guthrie* Date 12-20-93

Surveyor's Michigan License No. 22435