

Donald W. Carlson  
Chairman

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

4-300

For corners in

Alger

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 45N R 21W

C10

T R

T R

T R

SURVEY &  
REMONUMENTATION

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

MAY 10 1995

COMMISSION

FILED

9:00 a.m.

APR 20 1995

DONALD W. KINNUNEN  
EG

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert L. Jamros, in a field survey on December 07, 1994, 19, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C10: PLS-Zelotes B. Searls, DS, 1850, Set Qr. Section Post- Fir 8", S.60 W., 9 links, Y.Birch 18", N.35 E., 34 links. Minneapolis, St. Paul and Sault Ste. Marie Railroad right of way map, October 27, 1901, Notes corner as being five feet west of the centerline of the railroad right of way. A.C.R.C., Geo. L. Depew, CS, 1919 alignment notes. Corner position shown 101.5 ft. west of centerline of road. No references given. Edwin Swan, RLS, 1948, alignment notes for the Eben - Trenary road, Alger County Road Commission. Corner is a standard Alger County brass capped monument and is 102.3 feet west of the centerline of the Eben - Trenary road.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C10: Found 1 3/4" GIP with 3 1/4" Brass cap marked to identify corner position, dated Nov. 9, 1917. Measured Alger County Road Commission station distances along the Eben-Trenary Road to locate corner. Corner position checks well with record distances. Corner position lies 26.5 ft. west of the centerline of an old Railroad grade and 102.5 ft. west of the centerline of the Eben-Trenary Road. Corner position is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C10: Stamped P.A. 345 in existing brass cap galvanized iron pipe monument. Established reference tree w/ BT sign, blazed, scribed and painted. Set PK nail for measure w/ Alum. I.D. washer in the following reference tree. Set six foot long steel fence posts as witness references. Cherry cluster 4,5 & 6", S.28 W., 48.63 feet, '1/4s BT', Steel Witness Post with sign, N.57 E., 49.23 feet, Steel Witness Post with sign, S.54 E., 46.54 feet, Steel Witness Post with sign, N.28 1/2 W., 42.98 feet, Steel Witness Post with sign, S.57 W., 1.3 feet. All bearings are magnetic.

Signed by

Robert L. Jamros  
25849

Date

12 April, 1995

Surveyor's Michigan License No.