

SURVEY & MONUMENTATION

JAN 18 2001

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000
Donald W. Kinnunen
Chairman

For corners in **SECTION**

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Alger
(County)

Located In:

Corner Code #

- | | | | | | |
|-------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 46N | R | 17W | I03 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling | S | | T | R | |
| in Section | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Section | S | | T | R | |
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on August 22, 2000,
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I03: PLS William Ives, DS, 1850. Set post corner of Sections 2, 3, 10 and 11. Sugar 22", S.61°W., 26 links. Sugar 18", N.64°E., 03 links. ***** Alger County. W.W. Gleason, CS, 1913. Set iron corner from original field notes. No references. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Found 2" iron pipe with 3" brass cap set by unknown party. Checks with double proportionate measurement within 9 links North and South and 2 links East and West. Elm 8" (S10 NBT) S.80°W., 20 links. Elm 8", (S11 NBT) S.48°E., 13.5 links. Liber 2, Page 198, Alger County corner records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I03: Found 2" iron pipe with 3" brass cap and 4"x4" Cedar post of the 1960 report. The 2 NBT's of the 1960 report are dead and down, badly decayed. Monument position as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I03: Existing 2" iron pipe with 3" brass cap as found. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Maple 12", S.61°W., 11.65 feet (S10 BT); Maple 10", N.27°W., 27.98 feet (S3 BT); Maple 10", N.44°E., 34.80 feet (S2 BT); Maple 12", S.49°E., 20.36 feet (S11 BT). Survey marker on 6 foot steel post, N.10°W., 1.5 feet. All bearings are magnetic.

Signed by

Robert L. Jamros

Date Dec. 17, 2000

Surveyor's Michigan License No.

25849

