

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 5 T 48N R 15W	14
	S T R	(GCDB 300620)
	S 5 T 48N R 15W	16
	S T R	(GCDB 260600)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

I, Stephan J. Szyszkoski, in a field survey on 06/30/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(14-Sec. 5) South 1/16 corner between Sections 4 and 5. Not previously monumented.

(16-Sec. 5) East 1/16 corner between Sections 5 and 8. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(14-Sec. 5) Established the position for the corner midway and on the Section line between Section corner 1325.66' south and Quarter corner 1325.66' north.

(16-Sec. 5) Established the position for the corner midway and on the Section line between Section corner 1332.11' east and Quarter corner 1332.11' west. The position falls on a steep side slope of a hill, about 20 or 30 feet up from the bottom.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(14) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Maple N18°W 6.8' mrkd "S1/16 BT"
8" Maple N79°E 22.05' do
9" Maple S20°E 15.55' do
10" Maple S44°W 44.35' do
E= 8061403.682 N= 200164.271

(16) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Hemlock S05°W 14.75' mrkd "E1/16 BT"
12" Hemlock S58°W 31.55' do
14" Hemlock N86°W 11.35' do
14" Maple N57°E 21.2' do
E= 8061001.900 N= 199754.914

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RK0012: N= 200478.710 m. E= 8059786.467 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/30/2014

For the Michigan Department of Natural Resources, Forest Resources Division

