

DEC 27 1999

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-8-1999

Heinrich Uecker
Chairman

For corners in **SECTION** **LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

Alger

(County)

Located In:

Corner Code #

05-166

1. Public Land Survey

T 48N R 15W

D5

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Section

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

FILED
TIME 1:30 p.m.

DEC 15 1999

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Robert L. Jamros, in a field survey on June 09, 1999, 19_____,
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, recovered, found
as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

D5: PLS * George E. Adair, DS, 1851. * Set quarter section post. * Beech 12", N.72 E., 30 links. * Hemlock 9", S.41 W., 14 links.
***** Michigan Department of Conservation, Forestry Division. * Dean C. DeLaMater, RLS, 1954. * Found corner that had been previously
located and perpetuated by Ray J. Brotherton, RLS. * Set 1" iron pipe with 4" brass cap. * 40" W.Pine stump, N.18 E., 29 links. * 36"
W.Pine stump, N.77 W., 89 links. * Liber 2, Page 70, Alger County Corner Records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D5: Located corner search area by calculated position and standard field survey methods. Found 1" iron pipe with 4" brass cap in good
condition. Also found both W.Pine stump BT's in very poor condition. No GLO evidence was found. Established new reference trees.
Existing corner monument as found is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D5: Existing 1" iron pipe with 4" brass cap. * Established the following reference trees with BT signs, blazed, scribed and painted. *
Set PK nails with aluminum I.D. washers for measure in the following: Balsam 5", S.53 E., 14.59 feet, "1/4s BT". * W.Pine 6", N.38 E.,
5.39 feet, "1/4s BT". * Maple 5", N.58 W., 15.63 feet, "1/4s BT". * W.Pine 5", S.50 W., 26.01 feet, "1/4s BT". * Survey marker sign on
6 foot steel post, S.62 E., 1.5 feet. * All bearings are magnetic.

Signed by *Robert L. Jamros*
Surveyor's Michigan License No. 25849

Date Dec 13 1999

