

# SURVEY & MONUMENTATION

JAN 18 2001

Approved by Alger County  
Land Survey Remonumentation  
Peer Group Under Act 345 of  
P.A. of 1980 On 12-13-2000

Donald W. Kinnunen  
Chairman

05-205

For corners in **SECTION**

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Alger  
(County)

Located In:

Corner Code #

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN  
REGISTER OF DEEDS  
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

- Public Land Survey
 

T	48N	R	15W	B01	✓
T	49N	R	15W	B13	
T		R			
T		R			
- Property Controlling in Section
 

S		T		R	
S		T		R	
- Miscellaneous Property in Section
 

S		T		R	
S		T		R	

- Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
- Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Robert L. Jamros, in a field survey on May 12, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

### A. Description of original monument and accessories and/or subsequent restoration:

**B01:** PLS John Burt, DS, 1841. Set quarter section post. Fir 6", N.72°E., 21 links. Fir 9", N25°W., 58 links. \*\*\*\*\* Michigan Department of Conservation, Forestry Division. Dean C. DeLaMater, RLS, 1954. Set 1" iron pipe with 4" brass cap at proportionate position between section corners. W. Pine stump 36", N.75°E., 50 links. W. Pine stump 30", S.65°W., 37 links. Liber 2, Page 68, Alger County corner records. \*\*\*\*\* No other subsequent restoration of record.

### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

**B01:** Found 1" iron pipe with 4" brass cap and 1 reference of the 1954 report in good condition. Other reference in N.E. bearing has been lost. Corner monument position lies 9.2 feet South and 13.4 feet West of proportional position between section corners. Existing corner monument as found is accepted as a careful and faithful reestablishment of the position of the original corner.

### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**B01:** Existing 1" iron pipe with 4" brass cap as found. Renewed existing reference with BT sign and paint. Established additional reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, W. Pine stump 30", S.75°W., 24.90 feet (NBT); R. Pine 8", S.85°E., 11.18 feet (1/4S BT); R. Pine 8", South 03°E., 33.63 feet (1/4S BT); W. Pine 6", N.18°W., 24.63 feet (1/4S BT). Survey marker sign on 6 foot steel post, S.60°W., 1.0 feet. All bearings are magnetic.

Signed by Robert L. Jamros

Date Dec. 17, 2000

Surveyor's Michigan License No. 25849

