

**JAN 18 2001**

Approved by Michigan  
Land Survey Monuments  
Peer Group Under Act 213 of  
P.A. of 1990 On 12-13-2000

Gerald W. Kinnunen  
Chairman

For corners in

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**

Filing Requirement of Act 74, Mich. P.A. 1970

Alger  
(County)

Located In:

Corner Code #

05-206

- |   |   |            |   |            |            |
|---|---|------------|---|------------|------------|
| 1. Public Land Survey                   | T | <u>48N</u> | R | <u>15W</u> | <u>C06</u> |
|   | T |            | R |            |            |
|   | T |            | R |            |            |
|   | T |            | R |            |            |
| 2. Property Controlling<br>in Section   | S |            | T |            |            |
|   | S |            | T |            |            |
| 3. Miscellaneous<br>Property in Section | S |            | T |            |            |
|   | S |            | T |            |            |

**FILED**  
TIME 8:50 AM

**DEC 20 2000**

**DONALD W. KINNUNEN**  
REGISTER OF DEEDS  
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Robert L. Jamros, in a field survey on April 18, 2000,  
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, recovered, found  
as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

**C06:** PLS Geo. E. Adair, DS, 1851. Set quarter section post. Beech 10", S.55°W., 46 links.  
Beech 10", N.57° 30' East, 91 links. \*\*\*\*\* Michigan Department of Conservation, Forestry  
Division. Dean C. DeLaMater, RLS, 1953. Set 1" pipe with 4" brass cap by proportionate  
measurement between section corners. W. Pine stub 32", N.59°W., 79 links. W. Pine stub 20",  
N.61°E., 34 links. Liber 2, Page 27, Alger County corner records. \*\*\*\*\* No other subsequent  
restoration of record.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

**C06:** Found 1" iron pipe with 4" brass cap and a 4" square post of 1953 report in good  
condition. References lost. Existing corner monument lies 2.9 feet South and 2.2 feet West  
of midpoint position between section corners and at the corner of a pine plantation.  
Existing corner monument is accepted as a careful and faithful reestablishment of the  
position of the original corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

**C06:** Existing 1" iron pipe with 4" brass cap found. Established reference trees with BT  
signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in  
the following: W. Pine 10", N.22°W., 81.89 feet (1/4S BT); W. Pine 10", N.68°E., 8.32 feet  
(1/4S BT); W. Pine 5", S.07°E. 49.75 feet (1/4S BT); R. Pine 14", S. 57°W., 71.35 feet (1/4S BT).  
Survey marker sign on 6 foot steel post, N.29°W., 1.0 feet. All bearings are magnetic.

Signed by Robert L. Jamros

Date Dec 17, 2000

Surveyor's Michigan License No. 25849

