

JAN 18 2001

Approved by Alger County
Land Survey Monumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000

Gerald Carlson
Chairman

05-221

For corners in SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Alger
(County)

Located in:

Corner Code #

1. Public Land Survey

T 48N R 15W M09

T 48N R 14W A09

T R

T R

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

I, Robert L. Jamros, in a field survey on October 19, 2000

do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M09: PLS William A. Burt, DS, 1841. Set post corner of Sections 24 and 25. Beech 5", S.30°W., 24 links. Beech 10", N.43°E., 15 links. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M09: Found 1 1/4" iron pipe set by unknown party. Area around iron pipe was searched for original evidence and references to the existing monument, nothing was found. Paint lines for timber cutting are evident to the North, West and South. Measurement to the East to a meander corner on the West shore of Grass Lake returns 8.93 chains against the original G.L.O. return of 8.97 chains. Measurement to the section corner to the North has a return of 80.07 chains, G.L.O. was 80.0 chains. Existing iron pipe as found is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M09: Set 2 1/2" x 30" Berntsen aluminum monument no. A1NB30 with 3 1/4" aluminum cap stamped to identify corner position. New monument was set over existing 1 1/4" iron pipe. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Hemlock 10", N.34°W., 9.10 feet (S24 BT); Beech 22", N.31°E., 34.15 feet (S19 BT); Hemlock 16", S.43°E., 17.06 feet (S30 BT); Hemlock 14", S.61°W., 46.12 feet (S25 BT). Survey marker sign on 6 foot steel post, N.85°E., 0.90 feet. All bearings are magnetic.

Signed by Robert L. Jamros Date Dec. 17, 2000
Surveyor's Michigan License No. 25849

