

**JAN 18 2001**

Approved by Alger County  
Land Survey Monumentation  
Poor Group Under Act 345 of  
P.A. of 1990 On 12-13-2000

Donald W. Kinnunen  
Chairman

For corners in **SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

05-218

Alger  
(County)

Located in:

Corner Code #

**FILED**

TIME 8:50 AM

**DEC 20 2000**

DONALD W. KINNUNEN  
REGISTER OF DEEDS  
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

- |                                    |   |     |   |     |       |
|------------------------------------|---|-----|---|-----|-------|
| 1. Public Land Survey              | T | 48N | R | 15W | M07   |
|                                    | T | 48N | R | 14W | A07 ✓ |
|                                    | T |     | R |     |       |
|                                    | T |     | R |     |       |
| 2. Property Controlling in Section | S |     | T | R   |       |
|                                    | S |     | T | R   |       |
| 3. Miscellaneous                   | S |     | T | R   |       |
| Property in Section                | S |     | T | R   |       |
4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5						3		2		
3												
4	7	8	9					10	11	12		
5												
6	18	17	16					15	14	13		
7												
8	19	20	21					22	23	24		
9												
10	30	29	28					27	26	25		
11												
12	31	32	33					34	35	36		
13												

I, Robert L. Jamros, in a field survey on October 25, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

**M07:** PLS William A. Burt, DS, 1841. Corner of Section 13 and 24 in pond. Tamarack 8", 1.56 chains North. W. Pine 18", 12.02 chains, South, of section corner in lake. These trees are notched for station trees. \*\*\*\*\* C.C.I. Co. T.J. McLaren, cruiser, 1966. Set meander post on East side of lake in boggy marsh 31 links East of corner. W. Pine 5", line tree, 99 links East of meander post in edge of timber. NBT's from this line tree. W. Pine 12", N.64°E., 19 links. W. Pine 6", S.52°E., 25 links. Unrecorded report. \*\*\*\*\* No other subsequent restoration of record.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

**M07:** North of small lake found Tamarack stub down with blaze face showing scribing "Cor. 1.56 S.". W. Pine 18", station tree 12.02 chains South, not found. Found W. Pine 5" line tree 1.30 chains East of corner and NBT's of same, meander post not found. Established corner position by single proportionate measurement between stump of Tamarack station tree (1.56 chains North) and section corner 1 mile South. Monumented decayed stump of station tree and established witness corner 50 feet East of corner position and 35.8 feet West of W. Pine 5" line tree (1966 report). Corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

**M07:** Set 2½" x 30" Berntsen aluminum monuments no. A1NB30 with ¾" aluminum caps stamped to identify relationship to section corner position. Established reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: **STATION TREE**, cap stamped "Cor. 103.2 Ft. S"; Hemlock 7", N.51°W., 9.97 feet (WC BT); Hemlock 5", N.74°E., 11.13 feet (WC BT); Hemlock 8", S.02°E., 5.80 feet (WC BT); Hemlock 5", S.43°W., 8.52 feet (WC BT). Survey marker sign on 6 foot steel post, S.36°E., 1.0 feet. **WITNESS CORNER**, cap stamped "Cor. 50 Ft. W."; Spruce 8", N.26°W., 29.41 feet (WC BT); Spruce 10", N.32°E., 30.30 feet (WC BT); W. Pine 24", N.72°E., 37.76 feet (WC BT); Spruce 10", S.16°E., 29.47 feet (WC BT). Survey marker sign on 6 foot steel post, S.45°, 0.80 feet. All bearings are magnetic. \*\*\*\*\* See sketch on back.

Signed by Robert L. Jamros Date Dec 17, 2000  
Surveyor's Michigan License No. 25849

