

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 9 T 49N R 13W	F4
	S 9 T 49N R 13W	5
	T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8				10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 5 09/09/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F4) Center of Section 9. Not established in the original survey.

(5-Sec. 9) North 1/16 corner, Section 9. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F4) Established the corner at the intersection of straight lines connecting opposite 1/4 corners. Found an iron pipe, not of record, S20E 27.6' from the position for the corner.

(5-Sec. 9) Established the corner midway and on a straight line between Center of Section 1307.71' south and Quarter corner 1307.71' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F4) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
12" twin Maple N66E 13.65' mrkd "CS BT"
10" Y.Birch N42W 27.65' do
8" Sugar S71W 17.15' do
7" Maple S51E 20.55' do
Bearings are magnetic.

(5) Set 1"IDx36" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
10" Cedar S01W 23.75' mrkd "N1/16 BT"
19" Hemlock S30W 25.9' do
9" Hemlock N03W 2.0' do
4" Maple S85E 12.35' do
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/01/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

