

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000
Michael Detweiler
Chairman

SECTION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Alger Located In: Corner Code #
(County)

1. Public Land Survey	T	49N	R	13W	I10
	T		R		
	T		R		
	T		R		
2. Property Controlling in Section	S		T	R	
	S		T	R	
3. Miscellaneous Property in Section	S		T	R	
	S		T	R	
4. Lot No. _____, Recorded Plat _____					
5. Private Claims _____					

05-196
FILED
TIME 8:50 Am
DEC 20 2000
DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI
Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on July 25, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2				
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I10: PLS Francis Colman, DS, 1851. Set quarter section post. Sugar 10", N.31°W., 29 links. Sugar 12", S.60°E., 18 links. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap. Placed midway and on line between section corners. 12" Blk. Cherry, (1/4S NBT) N.66°W., 157 links. 12" Blk. Cherry, (1/4S NBT) S.61°E., 149 links. Liber 2, Page 94, Alger County corner records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I10: Found 1" iron pipe with 4" brass cap and 2 existing N.B.T's of the 1960 corner report in good condition. Corner monument as found lies 0.2 feet West and 1.1 feet South of the midpoint on line between section corners. Position of the existing monument is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I10: Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT's with BT signs and paint. Established new reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, Cherry 18", N.61°W., 103.90 feet; Ex. NBT, Cherry 18", S.58°E., 98.75 feet; Cherry 18", N.08°E., 78.71 feet (BT); Cherry 14", S.53°W., 76.24 feet (BT). Survey marker sign on 6 foot steel post, S.78°W., 1.5 feet. All bearings are magnetic.

Signed by Robert L. Jamros
Surveyor's Michigan License No. 25849

Date Dec. 17, 2000

