

JAN 18 2001

Approved by Alger County
Land Survey Monumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000

Herold C. Codrington
Chairman

FILED

05-199

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

For corners in **SECTION**

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Alger

(County)

Located In:

Corner Code #

- | | | | | | |
|------------------------------------|---|------------|---|------------|--------------|
| 1. Public Land Survey | T | <u>49N</u> | R | <u>13W</u> | <u>I13</u> ✓ |
| | T | <u>48N</u> | R | <u>13W</u> | <u>I01</u> |
| | T | _____ | R | _____ | _____ |
| | T | _____ | R | _____ | _____ |
| 2. Property Controlling in Section | S | _____ | T | _____ | _____ |
| | S | _____ | T | _____ | _____ |
| 3. Miscellaneous | S | _____ | T | _____ | _____ |
| Property in Section | S | _____ | T | _____ | _____ |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert L. Jamros, in a field survey on August 24, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I13: PLS John Burt, DS, for William A. Burt, DS, 1841. Set post corner of Sections 34 and 35. Sugar 8", N.14°E., 45 links. Birch 17", N.14°W., 15 links. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap from G.L.O. Sugar BT, N.14°E., 45 links, green and standing. Chopped out around both faces. H. Maple 13" (S3 NBT) S.17°W., 53 links. S. Maple 13" (S35 NBT) N.75°E., 16.5 links. H. Maple 9" (S24 NBT) N.58°W., 38 links. Liber 2, Page 87, Alger County corner records. No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I13: Found 1" iron pipe with 4" brass cap and 2 NBT's of the 1960 report in good condition, with third NBT being removed by logging. Found 2 other witness trees to this corner by unknown. Located G.L.O. Maple BT, now a 30" stub, 40 feet high and hollow. Existing corner position with monument is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I13: Existing 1" iron pipe with 4" brass cap. Renewed existing reference trees with BT signs and paint. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, Maple 16", N.82°E., 11.29 feet (blaze scars); Ex. BT, Maple 12", S.52°W., 17.61 feet (blaze scars); Ex. NBT, Maple 20", N.52°W., 25.67 feet (blaze scars); Ex. BT, Maple 12", N.10°E., 11.91 feet (blaze scars). Survey marker sign on 6 foot steel post, S.88°W., 1.5 feet. All bearings are magnetic.

Signed by Robert L. Jamros
Surveyor's Michigan License No. 25849

Date DEC 17, 2000

