

JAN 18 2001

SECTION

For corners in

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1990 On 12-13-2000

Donald W. Kinnunen
Chairman

05-200

Alger
(County)

Located In:

Corner Code #

- | | | | | | |
|---------------------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 49N | R | 13W | J11 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | | |
| | S | | T | | |
| 3. Miscellaneous Property in Section | S | | T | | |
| | S | | T | | |
| 4. Lot No. _____, Recorded Plat _____ | | | | | |
| 5. Private Claims _____ | | | | | |

FILED

TIME 8:50 Am.

DEC 20 2000

DONALD W. KINNUNEN
REGISTER OF DEEDS
ALGER COUNTY, MI

Register of Deeds Stamp & File Number

I, Robert L. Jamros, in a field survey on July 25, 2000,
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

J11: PLS Francis Colman, DS, 1851. Set quarter section post. Fir 12", N.70°W., 12 links. Maple 8", S.33°E., 14 links. ***** Michigan Department of Conservation, Forestry Division. Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap midway and on line between section corners. Blk. Cherry 10", (1/4S NBT) N.40°W., 89.5 links. Forked Blk. Cherry 12", (NBT) N.57°E., 45.5 links. Liber 2, Page 89, Alger County corner records. ***** No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J11: Found 1" iron pipe with 4" brass cap and both NBT's of the 1960 report in good condition. Corner monumented as found lies 0.5 feet South and 4.2 feet East of the midpoint position between section corners. No original corner evidence found. Existing corner monument as found is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J11: Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT's with BT signs and paint. Established additional reference trees with BT signs, blazed, scribed and painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, Blk. Cherry 16", N.38°W., 30.0 feet (blaze scars); Forked Blk. Cherry 16", N.63°E., 58.98 feet (blaze scars); Blk. Cherry 8", S.59°W., 28.93 feet (1/4S BT); Blk. Cherry 6", S.49°E., 31.25 feet (1/4S BT). Survey marker sign on 6 foot steel post, S.33°W., 1.5 feet. All bearings are magnetic.

Signed by

Robert L. Jamros

Date

Dec. 17, 2000

Surveyor's Michigan License No.

25849

