

JAN 18 2001

## SECTION

For corners in

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Approved by Alger County  
Land Survey Remonumentation  
Peer Group Under Act 345 of  
P.A. of 1990 On 12-13-2000

Hugh McClellan  
Chairman

05-201

FILED

TIME 8:50 AM

DEC 20 2000

DONALD W. KINNUNEN  
REGISTER OF DEEDS  
ALGER COUNTY, MI

Register of Deeds Stamp &amp; File Number

Alger (County)	Located in:	Corner Code #
1. Public Land Survey	T 49N R 13W	K10
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Section	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

I, Robert L. Jamros, in a field survey on July 27, 2000,  
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, recovered, found  
as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

**K10:** PLS Francis Colman, DS, 1851. Set quarter section post. Maple 10", N.35°W., 18 links.  
Maple 14", S.19°E., 28 links. \*\*\*\*\* Michigan Department of Conservation, Forestry Division.  
Billy D. Buckler, RLS, 1960. Set 1" iron pipe with 4" brass cap midway and on line between  
section corners. W. Pine 18" (¼S NBT) S.45°E., 113.5 links. W. Pine 8" (¼S NBT) S.08°E., 97  
links. Liber 2, Page 96, Alger County corner records. \*\*\*\*\* No other subsequent restoration  
of record.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

**K10:** Found 1" iron pipe with 4" brass cap and both NBT's of the 1960 report in good  
condition. Corner monument as found lies 1.1 feet West and 2.8 feet South of midpoint  
position between section corners. No original corner evidence found. Existing corner  
monument found is accepted as a careful and faithful reestablishment of the position of the  
original corner.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**K10:** Existing 1" iron pipe with 4" brass cap as found. Renewed existing NBT's with BT signs  
and paint. Established additional reference trees with BT signs, blazed, scribed and  
painted. Set PK nails for measure with aluminum I.D. washers in the following: Ex. NBT, W.  
Pine 26", S.08°E., 64.24 feet (blaze scars); Ex. NBT, W. Pine 34", S.50°E., 75.80 feet  
(blaze scars); W. Pine 4", South 50°W., 1.20 feet (BT); W. Pine 6", N.27°E., 20.18 feet  
(BT). Survey marker sign on 6 foot steel post, N.70°W. 1.4 feet. All bearings are magnetic.

Signed by Robert L. Jamros Date Dec. 17, 2000  
Surveyor's Michigan License No. 25849

