9

11

14

23

26

35

12

13

24

25

36

MAR 07 2000

ALLEGAN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE 00 FEB -1 AN 8: 40

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

<u> </u>			4		
Fο	r corners in				
Allegan			Located In:	Corner Code #	l
	- (County)				
1.	Public Land Survey		T2N R16W	LM-7, Sequence	
	,		TR	No. 3	
			T R		
			T R	Section 24	
2.	Property Controlling	S	T R	Cangog Trom	
	in Section	S	T R	Ganges Twp.	

Yayar Le. C. 120%

Register of Deeds Stamp & File Number

O.

21

28

33

10

15

27

D Ε F G Н

20

29

32

В С

18

19

30

1 2

3

Δ

5

ó

7

8

9 10

11

12 31

13

, Recorded Plat 5. Private Claims

I, Steve Lampen in a field survey on December 22, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned In lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: M-7

GLO -1831 - L. Lyon Set Post Tamarack 6 S 4 W 54 Tamarack 5 N 72 W 34

3. Miscellaneous Property in Sec.

GLO for A-7, T2N, R16W, West between Sec.'s 18 $\stackrel{\circ}{a}$ 19 73.40 to W boundary 32 lks S of post and set post corner Sec.'s 18 & 19 $\,$

No other records recovered

Description of corner evidence found and/or method applied in restoring or reestablishing corner: B. M-7 No monumentation found at corner. Re-established corner 21.12' (GLO jog) North of found corner at A-7, T2N, R15W on the extension Northerly of A-7 and M-8. Corner falls in large North and South drain. Set an Allegan County Remonumentation iron and yellow cap at a witness corner 25.0' West of M-7 on the North line of

See sketch on back.

Section 24.

The re-established position of M-7 is accepted as a careful and faithful re-establishment of the position of The original corner.

Approved by the Allegan County Remonumentation Peer Group on December 28, 1999.

Traversed 2583' on road

APPROVED REMONUMENTATION CORNER P.A. 345 OF 1990

ALLEGAN COUNTY DATE APPROVED OSC. 28, 1993 COUNTY REP. July 1. Clarify

Description of monument for corner and accessories established to perpetuate locating the position of the corner: LM-7, Sequence No. 3. Allegan County Remonumentation iron and cap 25.0' West of M-7 on the North line of Section 24.

Azimuth = Michigan State Plane grid direction 22" Maple remonumentation tag in W side 6° 56' 43.99 24" Maple remonumentation tag in W side 345° 41' 120.27 198° 48' 18" Maple remonumentation tag in E side 104.94 SE corner building foundation 320° 22' 188.99 Centerline E and W asphalt road pavement 180° 20' 129° 51' A-7, T2N, R15W 32.78 M-7, T2N, R16W 89° 45' 25.00 Centerline bridge is 20' S and 35' E

LA SHAME

Signed by Steven Lampen Surveyor's Michigan License No. 37279

Date DECEMBER 31, 1999

RFL WOLLOW N

MAR 0 7 2000

SECTION

