

# REMONUMENTATION

APR 25 1995

## ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

### COMMISSION

Located In: Allegan (County) Corner Code #

1. Public Land Survey T     R     D-13 (witness)  
T     R     Other # 1  
T     R      
T     R    

2. Property Controlling S 32 T 3N R 13W S Sec. line  
in Section S     T     R     Sec 32  
3. Miscellaneous S     T     R     Monterey Twp.  
Property in Sec. S     T     R    

1994 DEC 30 PM 12:16  
J. A. Clapp  
REGISTER OF DEEDS  
ALLEGAN COUNTY, MICHIGAN

FILED

Register of Deeds Stamp & File Number

4. Lot No.    , Recorded Plat      
5. Private Claims    

John P. Clapp December 12, 94

I, John P. Clapp, in a field survey on December 12, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

#### A. Description of original monument and accessories and/or subsequent restoration:

This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner. This monument was established on a survey for the Dumont Lake Road Alignment on May 25, 1984 by Tri-County Land Surveys, P.C.

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Intersection of the South line of Section 32 and the centerline of Dumont Lake Road  
Found 3/4" steel bar in monument box. This position not established by original government surveyors.  
This monument is accepted as the best available evidence of the position of the corner.

APPROVED REMONUMENTATION CORNER  
P.A. 345 OF 1990  
ALLEGAN COUNTY  
DATE APPROVED 12-13-94  
COUNTY REP. John P. Clapp

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Intersection of the South line of Section 32 and centerline of Dumont Lake Road  
Set A.C. Remon Iron and Cap in Monument Box  
A.C. Remon Tag & Nail in W Side Power Pole AZ. 9° 203.90'  
SW Corner House Foundation AZ. 165° 169.59'  
SE Corner Garage AZ. 55° 114.74'  
NW Corner House AZ. 256° 107.64'

Signed by John P. Clapp Date Dec 13, 1994  
Surveyor's Michigan License No. 14091

