

Allegan County Remonumentation  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Allegan  
(County)

Located in:

Corner Code ~~11~~

- |                         |                          |                      |
|-------------------------|--------------------------|----------------------|
| 1. Public Land Survey   | T <u>4N</u> R <u>13W</u> | <u>E-11 (NE, 32)</u> |
|                         | T _____ R _____          | <u>Salem Twp.</u>    |
|                         | T _____ R _____          | _____                |
|                         | T _____ R _____          | _____                |
| 2. Property Controlling | S _____ T _____ R _____  | _____                |
| in Section              | S _____ T _____ R _____  | _____                |
| 3. Miscellaneous        | S _____ T _____ R _____  | _____                |
| Property in Sec.        | S _____ T _____ R _____  | _____                |

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, John C. Bueche, in a field survey on October 26, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules theretofore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-11 1" iron, LCRC  
L1, P124, 1971, 1977  
Tw. Oak N 50° E 69.2'  
PP S 50° W 58.2'  
Gas line marker  
N 45° W 43.3'  
NW cor. hse. S 50° E 127.3'  
2640.29' N to E 1/4 cor.  
2634.66' W to S 1/4 cor.

SW cor. hse. fnd.  
NE 98.38'  
18" Oak NW 51.9'  
Same wit. (bearing & distance) from many sources

No date  
St. sign SSW 21.4'  
TP SW 33.1'  
Fence cor. NE 36.6'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-11 Found 1 1/4" pipe in Mon. Box in bit., down 3"  
Tw. Oak N 50° E 69.2' (face)  
PP S 50° W 58.2' (face)  
NW cor. hse. S 50° E 127.3'  
SW cor. hse. fnd.  
NE 98.38'

And is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-11 Placed Allegan Co. Remon. Cap in side of 1 1/4" pipe in Mon. box  
NE cor. conc. base for MBT box S 60° W 53.47'  
Top C/L MBT box N 40° W 55.30'  
Conc. Nail & Allegan Co. Remon. Tag in SE side 28" dbl. Oak N 55° E 70.22'  
SW cor. hse fnd. N 40° E 98.32'  
NW cor. hse fnd. S 40° E 127.08'  
C/L gravel road S & N, W 7'±  
C/L bit. road E-W, S 2'±  
Meas. by hand

Signed by


John C. Bueche  
13027

Date

Oct 26, 1993

Surveyor's Michigan License No.

LIBER 004 PAGE 236



FORM APPROVED BY MICHIGAN ASSOCIATION OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1982