

SURVEY & REMONUMENTATION

APR 25 1995

ALLEGAN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

Allegan (County)

Located In:

Corner Code #

1. Public Land Survey

T 4N R 45W

A-10-W1/4 Cor

T R

Sec 30

T R

Fillmore Twp.

T R

2. Property Controlling

S T R

in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, John P. Clapp, in a field survey on December 12, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-10 Recorded in Liber 3,

Page 195, Aug. 25, 1978

Set 1/2" Steel Rod from Co.

Surveyor's Records

24" Butternut W 40.56'

NE Cor Porch S30°W 107.33'

Power Pole S60°E 56.60'

NE Cor Hse. S70°E 114.72'

A-10 Recorded in Liber 4, Page 15, Mar 13, 1987

Set iron from County Surveyor Records

24" Butternut W 40.56'

NE Cor Porch S30°W 107.33'

Power Pole S60°E 56.60'

NE Cor Hse S70°E 114.72'

Iron N 3.30'

A-10 This position not established by original government surveyors.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

A-10

Found 1/2" steel bar in monument box. This position not established by original government surveyors. This monument is accepted as the best available evidence of the position of the corner.

NE Corner House Foundation

AZ. 115° 114.75'

Found Nail in S Side 26" Tree

AZ. 271° 40.59'

Found Nail in SW Side Power Pole

AZ. 133° 51.72'

APPROVED REMONUMENTATION CORNER

P.A. 345 OF 1990

ALLEGAN COUNTY

DATE APPROVED 12-13-94

COUNTY REP. John P. Clapp

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-10

Set A.C. Remon Iron and Cap in Monument Box on Township line.

A.C. Remon Tag & Nail in S Side 34" Nut Tree

AZ. 81° 233.44'

A.C. Remon Tag & Nail in Side 14" Pear Tree

AZ. 332° 150.54'

A.C. Remon Tag & Nail in WSW Side 26" Maple

AZ. 165° 108.86'

NE Corner Foundation of House

AZ. 115° 114.75'

M-10, T4N, R16W

AZ. 0° 3.30'


Signed by John P. Clapp

Date Dec. 13, 1994

Surveyor's Michigan License No. 14091

W:\Docs\Surv\Remon.doc

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, 1971



0005 PAGE 086