

ALLEGAN COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Allegan (County) Located in: Corner Code #

1. Public Land Survey T4N R16W J-2
Center, Sec. 2
Laketown Twp.
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat
5. Private Claims

I, Steven Lampen, in a field survey on March 23, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

J-2
GLO
This position not established by GLO
LCRC L 2-P 41 1972
3/4" iron in mon. box
Spike in 36" Maple ENE 98.71'
Nail in power pole SSE 94.51'
Spike in 20" Maple SW 63.23'
KVO SURVEY
1" rod in mon. box
Power pole SE 94.52'
NW corner house foundation SSW 72.06'
30" Maple SW 63.36'
Steel fence N 37.28'

LCRC L 1-P 313 1972
1 1/4" pipe
16" Maple S 50° W 62.70'
NW corner house S 5° W 72.00'
Power pole S 60° E 94.20'

Old County Survey Notes
Show iron at J-2

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-2
Found iron in monument box. This position was not established by original Government Surveyor's. This monument is accepted as the best available evidence of the position of the corner

Spike in 36" Maple ENE 98.71' 1 1/4" pipe Power pole SE 94.52'
Nail in power pole SSE 94.51' 16" Maple S 50° W 62.70' NW corner house foundation 72.06'
Spike in 20" Maple SW 63.23' NW corner house S 5° W 72.00' 30" Maple SW 63.36'
Power pole S 60° E 94.20' Steel fence N 37.28'

APPROVED REMONUMENTATION CORNER
P.A. 345 OF 1990
ALLEGAN COUNTY


DATE APPROVED 11-14-95
COUNTY REP. [Signature]

Traverse 5105' off road, 5320 feet on road

Approved by Allegan Co. Remon. Peer Group on November 14, 1995

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-2
Found iron in mon. box and set Allegan Co. Remon. iron and cap in mon. box.
AZ = MI State plane grid direction
J-1 0° 46' 09" 2431.08'
J-3 180° 03' 12" 2673.90'
I-2 270° 43' 03" 2649.64'
K-2 90° 46' 08" 2670.40'
NW corner house, brick 182° 30' 72.22'
NE corner house, brick 155° 15' 85.56'
10" Maple, Remon tag SE side 26° 07' 65.18'
14" Maple, Remon tag NW side 51° 34' 95.63'



Signed by Steven Lampen

Date November 14, 1995

Surveyor's Michigan License No: 37279

USE 0005 PAGE 227