

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Alpena</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 29N R 6E	I-6
	T 29N R 6E	K-6
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Num

4. Lot No. , Recorded Plat

5. Private Claims

I, Carl T. Kiiskila, in a field survey on July 02, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-6	GLO set section post.	K-6	GLO set section post.
Wit:	Yellow Pine 28" S 53° E 18 links	Wit:	Yellow Pine 18° N 74° E 18 links
	Yellow Pine 26" N 76° W 39 links		Soft Maple 6" S 14° W 26 links

Earl T. Lewis, LS #27452, February 1993 Certificate shows he found an existing pipe for the East quarter corner of Section 14.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-6	Reestablished the West quarter corner Section 14 from probable original GLO bearing tree stump remains.	K-6	Found a 2" pipe at a fence intersection.
	Yellow Pine 28" S 53° E 18 links (11.9')		
	Yellow Pine 26" N 76° W 39 links (25.7')		
	Distances North and South fit reasonably well with GLO distances.		

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-6	Set 1" x 32" iron pipe with aluminum DNR monument cap and set carsonite marker post.	K-6	Set 5/8" x 32" rerod with cap inside of found 2" iron pipe and set carsonite marker post.
Wit:	Set nail in 18" Oak S 60° E 37.29'	Wit:	Set nail in 5" Ash N 75° W 25.32'
	Set nail in 5" Oak N 32° E 26.67'		Set nail in Maple clump N 32° W 46.69'
	Set nail in 4" Ash West 20.16'		Set nail in 11" twin Ironwood N 4° W 29.74'
	Set nail in 10" Balsam S 16° W 16.59'		Set nail in 3" Red Maple N 88° E 27.57'
	North-south smooth wire East 15' ±		
	Centerline north-south trail road East 47' ±		

Signed by Carl T. Kiiskila  
Surveyor's Michigan License No. 33981



Date 6-14-99