LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:		·	
Alpena	Located In	Corner Code #	A 8
(County)			42
1. Public Land Survey	T 29N R 08E T 29N R 08E	- 1-2	16
Property Controlling in Section	STR		
3. Miscellaneous	S I R	-	
Property in Section	S T R R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G H I J K L M
5. Private Claims: _			2 6 5 4 3 2 1
I, <u>Carl T. Kiiskila</u> , in a field survey on <u>June, 24 2010</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			
A. Description of original monument and accessories and/or subsequent restoration:			
<u>l-2</u> – Quarter corner comm. to sec.'s 2 & 3, T29N, R08E <u>l-3</u> – Section corner comm. to sec.'s 2,3,10 &11, T29N, R08E			
1839 – GLO – Lewis Claison – Set qr. Sec. post. W. Pine 12" S45°W 16 links Cedar 7" N40°E 07 links 1911 – CSR – p.24 – Joseph W. McNeil – ¼ Cor. sec. 2&3, cor. plain our O.B.T. standing. W. Pine 12" S45°W 16 links; other tree down. Set new cedar stake for ¼ cor. and made N.W.T. Cedar 7" N69°E 21 ½ links 2004 – Cert. of Survey – L. 3, p.572 – Duane R. MacNeill, P.S.#19237 – Set 1" Pipe w/cap. 2006 – Cert. of Survey – L. 3, p.692 – Duane R. MacNeill, P.S.#19237 – Found 1" pipe w/cap. 2010 – Cert. of Survey – unrecorded – Wayne T. Lewis, P.S.#41922 – Exist 1" pipe w/cap#19237 – N50°E 34.43' 15" R. Pine; S75°W 9.50' Steel Fe. Cor. Post; S60°W 20.37' 20" Cedar; S10°W 11.93' 2" Tamarack		W. Pine Y. Pine Postaline N10 Solution N10 Solutio	O – Lewis Claison – Set post secs. 2,3,10&11 12" N60°E 57 links 22" S42°W 75 links R – p.21 – Joseph W. McNeil shows corner no wits. C.R.C. L. 1,P. 21 D. Marlatt P.S.#18660 fd 1" pipe d 1' in road also pipe 7' to NW. O'W 47.18' 18" Norway Pine o'W 51.2' 13" Norway Pine o'W 43.32' 20" Norway Pine ert. of Survey – L. 3, p.692 – Duane R. MacNeill, 237 – Found rerod. ert. of Survey – L. 3, p.700 – Duane R. MacNeill, 237 – Found rerod.
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:			
<u>l-2</u> – Quarter corner con	nm. to sec.'s 2 & 3, T29N, R08E	<u>I-3</u> – Section	corner comm. to sec.'s 2,3,10 &11, T29N, R08E
Found 1" pipe w/P.S. cap#19237 per Cert. of Survey – L.3, p.572. Accepted found pipe as a careful and faithful Dua reestablishment of the position of the original corner. Found no other evidence to dispute the location for the corner.		Duane R. M	ar flush with road fitting D. Marlatt's witnesses and acNeill's survey in section 3.
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: <u>I-2</u> – Quarter corner comm. to sec.'s 2 & 3, T29N, R08E <u>I-3</u> – Section corner comm. to sec.'s 2,3,10 &11, T29N, R08E			
1" dia. Pipe with P.S	cap #19237 in center of pipe	Added	d P.S. cap #33981 to found ½" bar
S57°E 100.22' to *S17°W 11.93' to *S53°W 20.35' to	fd. N&T on SE side 18" W. Pine o set N&T on NE side 30" W. Pine fd. N&T on E side 3" Tamarack ofd. N&T on SE side 17" Cedar fd. 3" dia. galv. pipe 5' tall	* S22°\ *S70°\ N58°\	33.85' to set N&T at fd N&T #41922 12"&16" twin Oak <i>N</i> 43.99' to set N&T at old N&T on E side 22" R. Pine <i>N</i> 51.85' to set N. side 16" R. Pine <i>N</i> 54.91' to fd. N&T at old N&T on W side 16" R. Pine <i>N</i> 47.72' to set N&T at fd N&T W side 21" R. Pine
* Previous recorded witness.			
C	and T Kirk	il zzzin	CARL KIISKILA
Surveyor's Michigan I	License No.: 33981		LAND SURVEYOR No. 33981
FORM APPROVED BY MICHIELD STATE BOOK OF PROFESSIONAL SURVEYORS JAN. 28, 1971			
Revised May 14, 1975 Revised Jan. 1983 Revised Oct. 1995			