

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Alpena
(County)

Located In

Corner Code #

1. Public Land Survey	T	29N	R	8E	H-2
	T	29N	R	8E	I-1
2. Property Controlling in Section	S	T		R	
	S	T		R	
3. Miscellaneous Property in Section	S	T		R	
	S	T		R	

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on July 12, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4			3		2		1	
3													
4	7		8		9			10		11		12	
5													
6	18		17		16			15		14		13	
7													
8	19		20		21			22		23		24	
9													
10	30		29		28			27		26		25	
11													
12	31		32		33			34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

H-2 – Center of Section 3, T29N,R08E

I-1 – Sec. Cor. comm. to sec.'s 2&3, T29N,R08E

This corner position was not established during the original Government Survey.

1839 – GLO – Lewis Claison intersected 0.99 lks W of post

Y. Pine 16 in S45°W 1.07
W. Pine 30 in S71°E 33

2006 – L.C.R.C. L.2,P.343 Daniel T. Kibbe P.S. #37278
Found a PK nail set by Wayne T. Lewis P.S.#41922
Set a 1/2" bar in a monument box after road reconstruction

S35°E 70.50' to 20" Spruce
S70°E 54.61' to 15" Oak
East 59.78' to 18" Spruce
N51°E 61.31' to 7" Oak

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

H-2 – Center of Section 3, T29N,R08E

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure (intersection of 1/4 lines).

I-1 – Sec. Cor. comm. to sec.'s 2&3, T29N,R08E

Found a 1/2" bar in a monument box fitting D. Kibbe's witnesses and W. Lewis's survey in section 3.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-2 – Center of Section 3, T29N,R08E

Set a stamped 2" aluminum cap on 5/8" x 34" rerod.

I-1 – Sec. Cor. comm. to sec.'s 2&3, T29N,R08E

1/2" bar in a monument box

Witnesses:

N51°E 40.35' to set N&T on SE side 10" Oak
S73°E 44.98' to set N&T on S side 13" Oak
S23°W 1.94' to set N&T on E side 8" Ash
N21°W 33.35' to set N&T on SW side 8" Ash
Set Blue Carsonite Post 1' North

Witnesses:

N80°E 59.86' to Fd. N&T on N side 24" Spruce
S80°E 54.61" to Fd. N&T on S side 20" Oak
S52°E 70.53' to Fd. N&T on N side 24" Spruce
N60°W 87.36' to set N&T on NE side 25" Oak

Signed by:

Carl T. Kiiskila

Date:

2/9/11

Surveyor's Michigan License No.:

33981

